

Kenneth

REF:

AIS / 23002829/kp

C

REC. BY:

ENT

SHO 9797J Yr. Regn: 09 20

Car / M.Cycle / Bus / Van / Lorry / Truck / Trailer or

Truck / Trailer or

Toy Priv 1798

Mr. White / R

213212 T/Radist: Insure

JTOKB3FU503092073

Good / Fair / Poor / Burnt

In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

NII / S/Rlm / STD A/Rlm or

F: 195/65R15

R:

EXNOVA / GY / FS / LIZA / MIC / OHT / PIR

OKO or Wani

9 mm

Front

Wheel

7

9 mm

Wheel

7

7/3/23

D.O.I. 20/3/2023

Engines: Frt / Rear / O/S / N/S / UIC / Roof

Rec. dls

Chassis frame / Body Structure affected

Date:

Estimated Cost:

C PWS / TP RES / OD RES / EVA / INV / MV

Taxi / Transport Vehicle No:

Workshop m/s

Tans Cab

Insured:

Policy No.

Class No.

Sum insured:

Excess:

(Driver's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.

Date of Market Value:

IDAC Incident Report:

Consistent?: Yes or No

GIA Report Seen:

Consistent?: Yes or No

Est. Inval:

02 days

Res.: Yes or No

Lum Sum:

L.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle:

Date / Time

Action / Instruction

M/3 01838.91 Calh

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Additional Insp (\$

No. of Trip:

Survey Fee

Transportation

S - RS

Part

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

NOT NOTICED
 Recovery B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD9797J

AAD2303-

81838.91

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

20 MAR 2023

SHD9797J

JTDKB3FU503092073

200303878K

TOYOTA

PRIUS GEN 4

7/2/2023

SMW51C/ Allianz

30/9/2020

PART

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, BACK DOOR TRIM
- 1 PANEL SUB-ASSY, BODY LOWER BACK

LIST

Bumper	\$	558.39	
Re	\$	19.43	X
nd/ht	\$	726.92	
Re	\$	49.25	
Re	\$	111.41	
Re	\$	111.41	
Re	\$	147.11	X
Re	\$	148.58	X
Re	\$	419.90	X
Re	\$	220.50	
Re	\$	304.92	X
Re	\$	290.43	X
Re	\$	31.50	
Re	\$	824.46	

TOTAL \$ 3,964.18
 25% \$ 991.04
\$ 2,973.13

SPECIAL NETT

1SET PARKING AID

- 1 REAR BUMPER CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO.
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING

Re	\$	700.00	X
Re	\$	65.00	605m
Re	\$	100.00	X
Re	\$	100.00	X
Re	\$	65.00	X
Re	\$	65.00	X
Re	\$	60.00	X
Re	\$	180.00	305m
Re	\$	150.00	X
Re	\$	200.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD9797J**AAD2303-**

1 WINDSCREEN INNER SPONGE SEAL

	\$	<i>na</i>	130.00	X
TOTAL	\$		1,815.00	
TOTAL PARTS	\$		4,788.13	

LABOUR

To rust-proofing of the affected areas.	\$	<i>na</i>	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	<i>2201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	<i>2004</i>
To transfer of tailgate fittings and conduct water seepage test.	\$	<i>na</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>4</i>	380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	<i>4</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
To check steering geometry and computer wheel alignment	\$	<i>4</i>	220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i>	170.00	X
TOTAL	\$		5,080.00	
OVERALL TOTAL	\$		9,868.13	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

2 days