

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
 SHD9797J

AAD2303-

NOT WITHHOLD
 RETURN BY PAINT

Vehicle No.:
 Chassis No.:
 Co UEN.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer:
 Date of Registration:

20 MAR 2023

SHD9797J
 JTDKB3FU503092073
 200303878K
 TOYOTA
 PRIUS GEN 4
 7/2/2023
 SMW51C/ Allianz
 30/9/2020

PART

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, BACK DOOR TRIM
- 1 PANEL SUB-ASSY, BODY LOWER BACK

LIST

Build	\$	558.39	—
	\$	19.43	✓
Ref/ht	\$	726.92	—
	\$	49.25	
	\$	111.41	
	\$	111.41	
	\$	147.11	
	\$	148.58	
	\$	419.90	X
	\$	220.50	
	\$	304.92	
	\$	290.43	
	\$	31.50	
	\$	824.46	
TOTAL	\$	3,964.18	
25%	\$	991.04	
	\$	2,973.13	

SPECIAL NETT

1SET PARKING AID

- 1 REAR BUMPER CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO.
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING

\$	700.00	X
\$	65.00	605N
\$	100.00	X
\$	100.00	X
\$	65.00	X
\$	65.00	X
\$	60.00	X
\$	180.00	705N
\$	150.00	X
\$	200.00	X

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHD9797J

AAD2303-

1 WINDSCREEN INNER SPONGE SEAL

	\$	nn	130.00	X
TOTAL	\$		1,815.00	
TOTAL PARTS	\$		4,788.13	

LABOUR

To rust-proofing of the affected areas.	\$	nn	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	2004
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4	380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	4	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	7	170.00	X

	\$	7	170.00	X
TOTAL	\$		5,080.00	

OVERALL TOTAL	\$		9,868.13	
---------------	----	--	----------	--

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
S. _____
Date _____

2 days