

(08/11/13) Wef

ASS. REC.-BY: *Marcus*

REF:

*CC4/A1523002830/Upa3***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

days

%

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \_\_ S + RS \_\_ SI

) Photos

) Others

TOTAL

N/S	O/S

*6/4/23 4/5 6200 inbound A Gen.*

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 6746758 Fax No: 67458520

Tax Reg No : 200006262D

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE No: SLF 8335H

1PC	REAR WINDSCREEN	11	30/13/23	5 days	\$1,866.10	X
1PC	REAR WINDSCREEN MOULDING	del	2/5 #6200		\$99.50	
1PC	TAILGATE	body ID		24/5/11	\$2,650.20	
1PC	TAILGATE 'VELLIRE' EMBLEM	su			\$105.10	X
1PC	TAILGATE WEATHERSTRIP	tw			\$388.90	
1PC	TAILGATE INNER LOCK	daye/shank			\$650.20	
1PC	TAILGATE INNER TRIM BOARD	de/cu			\$955.80	
1SET	TAILGATE INNER TRIM BOARD CLIPS	del			\$50.00	
2PCS	TAILGATE REFLECTORS @\$ 689.10	11			\$1,378.20	X
1PC	TAILGATE OUTER GARNISH	11			\$855.20	X
1PC	REAR BUMPER	DD		13/5/22	\$1,450.00	
2PCS	REAR BUMPER SIDE RETAINERS @\$85.00	11			\$170.00	X
1SET	REAR BUMPER CLIPS	del			\$50.00	
1PC	REAR BUMPER TOW COVER	11			\$48.00	X
2PCS	REAR BUMPER PDC SENSORS @\$265.00	no/funoln			\$530.00	
2PCS	REAR BUMPER REFLECTORS @\$98.00	11			\$196.00	X
1PC	REAR END PANEL	DD			\$911.20	
1PC	REAR END PANEL TOP GARNISH	tw			\$245.20	
2PCS	TAILLAMPS @\$950.10	11			\$1,900.20	X
2PCS	TAILLAMP LOWER GARNISHS @\$650.10	11			\$1,300.20	X
1PC	REAR ANTENNA SENSOR	11			\$226.20	X
1PC	REAR BUZZER SENSOR	11			\$210.50	X
1PC	REAR FLOOR PANEL	11			\$1,125.50	X
					\$16,862.20	

## S.NETT

1PC	REAR WINDSCREEN SEALANT	del	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	del	\$50.00	40
1PC	REAR LICENCE PLATE	11	\$50.00	X

## TO CHECK WIRING

TO DISMANTLE & REPLACED REAR PDC SENSOR

TO DISMANTLE & REFIX REAR WINDSCREEN

TO DISMANTLE & REFIX TAILGATE MECHANISM

TO DISMANTLE & REFIX CUSHION UPHOLSTERY

TO SPRAY RUST PROOFING

LABOUR FOR PANEL BEATING & REPLACED PARTS

TO PUTTY & SPRAY PAINTING

total \$20,342.20

7/11/13  
259  
5708.34