



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2001779358-01	Date of Loss:	15/03/2023
Vehicle Reg. No.:	SNB6031U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAY MIN WEI		
Driver:	SOH HAN RUI HALLEY		

Make/Model:	M.G. HS, 1.5 (A)	Vehicle Reg. Date:	31/08/2021
Vehicle Colour:	BLACK		
Engine No:	15E4E8AGM4010008	Chassis No:	LSJA24U9XMN081109
Odometer:	20000 KM		

Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		

p/p \$12243.80
not allowed
acc
Excess \$1100
Take the before party
5 days.
20/3/23

Remarks:	VEH IN WORKSHOP
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)

COST OF CLAIMS	Amount
Parts	10,618.10
Miscellaneous Items	0.00
Labour	2,250.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	12,868.10
- Excess (S\$)	600.00
(S\$)	12,268.10
+ GST 8.00% (S\$)	981.45
Nett Amount (S\$)	13,249.55

This claim is handled by: **JOEL NG**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

13319.10

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 17 Mar 2023)

Parts: M1-SUV

M.G. HS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SNB6031U/17/03/2023 16:31

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER DIS	0.00	0.00	*900.00 F
2	2		*FRONT BUMPER SIDE RETAINER o/s sent n/sam 58	0.00	0.00	*116.00 F 17c
3	1		*FRONT BUMPER CLIP ne	0	0.00	*50.00 FS
4	1		*FRONT BUMPER RIVET ne	0	0.00	*50.00 FS
5	1		*FRONT BUMPER TOW COVER To.1	0.00	0.00	*75.00 F
6	1		*FRONT BUMPER LOWER GARNISH ne DIS	0.00	0.00	*385.00 F 22c
7	1		*FRONT BUMPER REINFORCEMENT 17	0.00	0.00	*650.00 F
8	1		*FRONT BUMPER TOP 27/12	0.00	0.00	*290.00 F
9	1		*O/S FOGLAMP CHROME ne	0.00	0.00	*125.00 F
10	1		*RADIATOR GRILLE ASSY ne	0.00	0.00	*850.00 F
11	1		*LOGO EMBLEM 17	0.00	0.00	*90.00 F X
12	1		*RADIATOR GRILLE BRACKET ne 260	0.00	0.00	*430.00 F
13	1		*O/S HEADLAMP holder ne	0.00	0.00	*2,200.00 F
14	1		*RADIATOR SUPPORT PANEL ne	0.00	0.00	*800.00 F
15	1		*RADIATOR SUPPORT PANEL TOP COVER 17	0.00	0.00	*180.00 F X
16	1		*RADIATOR SUPPORT PANEL TOP COVER STICKER 17	0	0.00	*50.00 FS X
17	1		*BONNET 27/3uc	0.00	0.00	*1,850.00 F
18	1		*BONNET CHASSIS STICKER ne	0	0.00	*50.00 FS
19	1		*O/S FRONT FENDER 3uc/3uc	0.00	0.00	*750.00 F
20	1		*O/S RAD AIR GUIDE To.1	0.00	0.00	*80.00 F

F=Franchise part. S=SpcNett.

1st duct RM cre		Sub Total (\$\$)	9,671.00
fog lamp RM ne / \$285 ✓		+ Margin on L,N Items 10.00% (\$\$)	947.10
		Total Parts (\$\$)	10,618.10

Falcon-Air Auto Services Pte Ltd/SNB6031U/17/03/2023 16:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK LIGHT AND WIRING	New	20 50.00
2	TO VAC, REOIL AND REGAS AIRCON	New	100 120.00
3	TO DIAGNOSE, REPROGRAM AND CLEAR CODE	New	60 280.00
4	LABOUR/PANEL BEATING	New	600 800.00
5	SPRAY PAINTING	New	800 1,000.00
Gross Labour Cost (\$\$)			2,250.00

Falcon-Air Auto Services Pte Ltd/SNB6031U/17/03/2023 16:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110

Website: www.falconair.com.sg Email: email@falconair.com.sg

P- 9558
102
P- 10513.80
S.N - 150
2- 1580
12243.80