

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/ C7/ 23002843/4923

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SM 89865

at Workshop m/s

Pauhi

of _____

Insured: _____

ABD 6147

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

860k

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: _____

3

days

Res.: Yes or No

Lump Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1070

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

2748 27429

Veh No:

SM 89865

Yr Regn:

23/02/18

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

CA /

ALS

Make:

Hyundai Elantra c.c 159 /

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

127559

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

KMHD 841CMJU 631414

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: _____

F: _____

215-45-17

R: _____

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

14/03/23

D.O.I. _____

17/03/23

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Reg 11k

3/5/23 1/5 @ 1550 informed Reg 11k (Used 2774.80, 642)

Date/Time, File Pass to?

1) 04/5 train

Date/Time, File Return to?

2) _____

☐

Preli. Report

☐

Final Report

Days Of Repair: _____

3

Resurvey No. of Trip: _____

1

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format: _____

MEN-TP

Lump Sum / L.B.T. (\$ _____)

1550

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

*Not Allowed
 here
 17/3/23
 4/5 & 1550
 who ph. Herry
 3 days*

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road
 Springleaf Tower #16-00
 Singapore 079909

TEL: 63896111

FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Your Ref No: TP 0323-7317

Claim Type: Third Party

Accident Date: 14/03/2023

TP Veh Reg No: GBD 614 J

Estimate No: EST1509461

Date: 14 Mar 2023

Policy No: MPC23P00061400

Veh Reg No: SJH8986S

Make/Model: HYUNDAI ELANTRA
 AD 1.6 GLS AT (AMS)

Chassis No: KMHD841CMJU631414

Engine No: G4FGJU137712

Reg. Date: 23/02/2018

Estimate Repair Cost to Vehicle No :SJH8986S

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	460.0000	1 PC	De 460.00	—
2 REAR BUMPER SIDE HOLDER - LH/RH	44.0000	2 PC	11 88.00	X
3 REAR BUMPER CLIPS	4.9000	10 PC	rec 49.00	—
4 REAR BUMPER REINFORCEMENT	295.0000	1 PC	Sc 295.00	X
5 REAR BUMPER REINFORCEMENT BRACKET TOP - LH/RH	12.0000	3 PC	11 36.00	X
6 REAR BUMPER REINFORCEMENT BRACKET (LOWER) - LH/RH	12.0000	3 PC	11 36.00	X
7 REAR BUMPER LOWER LIP (BLACK)	251.0000	1 PC	1 251.00	X
8 REAR BUMPER REFLECTORS - LH/RH	42.0000	2 PC	11 84.00	X
9 REAR BOOT ELNATRA WORDINGS	49.0000	1 PC	rec 49.00	2
10 REAR BOOT RUBBER	93.0000	1 PC	11 93.00	X
11 REAR END PANEL	455.0000	1 PC	1 455.00	X
12 REAR END PANEL TOP GARNISH	60.0000	1 PC	11 60.00	X
			1,956.00	
		Less 20%	391.20	1,564.80
Special Net				
13 REAR BUMPER SENSOR	220.0000	1 PC/set	220.00	200
14 REAR BUMPER CENTER LAMP	200.0000	1 PC	11 200.00	X
15 REAR BUMPER LOWER SPOILER	400.0000	1 PC	cre 400.00	—
			820.00	820.00
Labour				
16 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	400
17 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	400
18 TO CHECK WIRING	30.0000	1 JOB	30.00	20
19 TO REMOVE, REPLACE / REFIT REAR BUMPER SENSOR	100.0000	1 JOB	100.00	50
20 TO REMOVE, REFIX REAR GARNISH	150.0000	1 JOB	150.00	60
21 TO TUFF-KOTE	60.0000	1 JOB	60.00	X
			1,940.00	1,940.00

*171.4
 202
 158/12*

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road

Springleaf Tower #16-00

Singapore 079909

TEL: 63896111

FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Your Ref No: TP 0323-7317

Claim Type: Third Party

Accident Date: 14/03/2023

TP Veh Reg No: GBD 614 J

Estimate No: EST1509461

Date: 14 Mar 2023

Policy No: MPC23P00061400

Veh Reg No: **SJH8986S**

Make/Model: HYUNDAI ELANTRA
AD 1.6 GLS AT (AMS)

Chassis No: KMHD841CMJU631414

Engine No: G4FGJU137712


Reg. Date: 23/02/2018

Estimate Repair Cost to Vehicle No :SJH8986S

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 4,324.80
			Add GST @ 8%	345.98
			Total Amount Payable	<u>SS 4,670.78</u>

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SIX HUNDRED SEVENTY AND CENTS SEVENTY EIGHT ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road I #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
 GST: 201006949C RCB NO: 201006949C

*Not Allowed
 her
 17/3/23
 4/54/1550
 who ph. Henry
 3 days*

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road
 Springleaf Tower #16-00
 Singapore 079909

TEL: 63896111

FAX: 6221033

ATTN: Motor Claim Department \ CHINA

Your Ref No: TP 0323-7317

Claim Type: Third Party

Accident Date: 14/03/2023

TP Veh Reg No: GBD 614 J

Estimate No: EST1509461

Date: 14 Mar 2023

Policy No: MPC23P00061400

Veh Reg No: SJH8986S

Make/Model: HYUNDAI ELANTRA

AD 1.6 GLS AT (AMS)

Chassis No: KMHD841CMJU631414

Engine No: G4FGJU137712

Reg. Date: 23/02/2018

*PAID 446.40
 SN 600.00
 VHS 930.00
 1936.40*

Estimate Repair Cost to Vehicle No :SJH8986S

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	460.0000	1 PC	460.00	✓
2 REAR BUMPER SIDE HOLDER - LH/RH	44.0000	2 PC	88.00	X
3 REAR BUMPER CLIPS	4.9000	10 PC	49.00	✓
4 REAR BUMPER REINFORCEMENT	295.0000	1 PC	295.00	X
5 REAR BUMPER REINFORCEMENT BRACKET TOP - LH/RH	12.0000	3 PC	36.00	X
6 REAR BUMPER REINFORCEMENT BRACKET (LOWER) - LH/RH	12.0000	3 PC	36.00	X
7 REAR BUMPER LOWER LIP (BLACK)	251.0000	1 PC	251.00	X
8 REAR BUMPER REFLECTORS - LH/RH	42.0000	2 PC	84.00	X
9 REAR BOOT ELNATRA WORDINGS	49.0000	1 PC	49.00	✓
10 REAR BOOT RUBBER	93.0000	1 PC	93.00	X
11 REAR END PANEL	455.0000	1 PC	455.00	X
12 REAR END PANEL TOP GARNISH	60.0000	1 PC	60.00	X
			1,956.00	
		Less 20%	391.20	
			1,564.80	
Special Net				
13 REAR BUMPER SENSOR	220.0000	1 PC	220.00	✓
14 REAR BUMPER CENTER LAMP	200.0000	1 PC	200.00	X
15 REAR BUMPER LOWER SPOILER	400.0000	1 PC	400.00	✓
			820.00	
Labour				
16 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	400 ✓
17 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	400 ✓
18 TO CHECK WIRING	30.0000	1 JOB	30.00	20 ✓
19 TO REMOVE, REPLACE / REFIT REAR BUMPER SENSOR	100.0000	1 JOB	100.00	50 ✓
20 TO REMOVE, REFIX REAR GARNISH	150.0000	1 JOB	150.00	60 ✓
21 TO TUFF-KOTE	60.0000	1 JOB	60.00	✓
			1,940.00	

430

no/tution

Repair Bootlid.

*548
 1,564.80
 446.40*

600

*200 ✓
 20 ✓
 50 ✓
 60 ✓*

Vehicle Details

Vehicle No.	Make / Model
SJH8986S	HYUNDAI / ELANTRA AD 1.6 GLS AT (AMS)
Vehicle Type :	Vehicle Attachment 1 :
P10 - Passenger Motor Car	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	KMHD841CMJU631414
Propellant :	Engine No. :
Petrol	G4FGJU137712
Motor No. :	Engine Capacity :
-	1591 cc
Power Rating :	Maximum Power Output :
-	93.8 kW (125 bhp)
Maximum Laden Weight :	Unladen Weight :
1800 kg	1345 kg
Year Of Manufacture :	Original Registration Date :
2018	23 Feb 2018
Lifespan Expiry Date :	COE Category :
-	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium :	COE Expiry Date :
\$41,400.00	22 Feb 2028
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
22 Aug 2023	22 Feb 2028
Inspection Due Date :	Intended Transfer Date :
22 Feb 2025	07 Mar 2023
CO2 Emission :	CEV/VES Rebate Utilised Amount :