



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: OH VALE			Ref: CS/HSB23002848/Knp3m4 Date: 04/04/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 7247Z	Veh. Inspected	SLT 8741U	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S3M04KNS	Excess (\$)	0.00	
Assign From	OH VALE	Assign Date	20/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GB71048295	Colour	METALLIC GREY	
Odometer	126706 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65R15	FALKEN	6 mm	
L/H Front Tyre	185/65R15	FALKEN	6 mm	
R/H Rear Tyre	185/65R15	FALKEN	7 mm	
L/H Rear Tyre	185/65R15	FALKEN	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	19/03/2023	Inspection Date	21/03/2023	
Survey held at	MASSIVE TRADING & AUTO BLK 5038 ANG MO KIO INDUSTRIAL PARK 2 #01-405 SINGAPORE 569541			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	