

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref : 23/23/VC05/027130 Date: 28<sup>th</sup> Mar 2023

Our Ref : CS/LPC23002850/Rny3e2

## M/s Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBF 6351S ACCIDENT ON 16/03/2023

Instruction was received to inspect the vehicle Reg. No. GBF 6351S. The inspection was conducted on 20/03/2023 at the premises of M/s Wearnes Automotive Pte Ltd, 249 Alexandra Road, Singapore 159935.

The following vehicle information was recorded:

Registration Number : GBF 6351S

Make/Model : Renault Kangoo II Express 1.6L AT ABS AB 2WD 6DR

Year of Registration : 2017 Body Colour : White

Chassis Number : VF1FW1UBA53790687

Engine Capacity : 1598 cc Speedometer Reading : 87570 km

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$13,416.90 (Sin Dollars: Thirteen Thousand Four Hundred Sixteen and Ninety Cents only.) (Exclude check items S\$16,935.60Nett) (Details see photographs enclosed)



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "uneconomical Total Loss".

| (a) | If the | vehicle | to be | "Total | Loss" |
|-----|--------|---------|-------|--------|-------|
|     | 3 / 1  |         |       |        |       |

Market Value

S\$ 34,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 18,538.00)

Nett Liability

S\$ 15,462.00

S\$ 15,462.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)
(Exclude check items \$\$16,935.60Nett)

S\$ 13,416.90

Nett Liability

S\$ 13,416.90

(a) - (b) =

(S\$ 2,045.10)

The amount of estimated saving of S\$2,045.10 if the vehicle to be written off as "**Total Loss**" instead of to be repair.

Vehicle Inspected By:

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU

R.K.EAU

MSc(Eng M), B Eng(Hons), PEng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA),

MIRTE,MIMI,MSAE,MCIARA, AM,NIJAAR(USA), AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.