



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: OH VALE		Ref: CS/HSB23002852/Aqp3e2 Date: 29/05/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHF 560Z	Veh. Inspected	SND 5236S
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04KLT	Excess (\$)	0.00
Assign From	OH VALE	Assign Date	20/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA VELLFIRE	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	JTNGF3DH608034164	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	TOYO	6 mm
L/H Front Tyre	235/50 R18	TOYO	6 mm
R/H Rear Tyre	235/50 R18	TOYO	6 mm
L/H Rear Tyre	235/50 R18	TOYO	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	17/03/2023	Inspection Date	20/03/2023
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	