

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SND5236S
VEHICLE MODEL : TOYOTA VELLFIRE
CHASSIS NO : JTNGF3DH608034164

2022 JAN

TP HSBC

Xiao Chen

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Defect</i>	1	\$ 889.10	\$ 889.10
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 140.20	\$ 280.40
3	REAR BUMPER TO COVER <i>Defect</i>	1	\$ 38.90	\$ 38.90
4	REAR BUMPER REFLECTOR LH <i>Defect</i>	1	\$ 121.30	\$ 121.30
5	REAR BUMPER UNDERCOVER LH <i>new</i>	1	\$ 145.60	\$ 145.60
6	REVERSE SENSOR <i>2 pieces damaged</i>	4	\$ 321.60	\$ 1,286.40
7	REVERSE SENSOR HOLDER <i>new</i>	4	\$ 25.00	\$ 100.00
8	REVERSE SENSOR WIRE HARNESS <i>new</i>	1	\$ 288.10	\$ 288.10
9	REAR END PANEL <i>Dented</i>	1	\$ 785.70	\$ 785.70
10	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 245.20	\$ 245.20
11	TAILLAMP LH <i>new</i>	1	\$ 661.90	\$ 661.90
12	TAILLAMP LOWER ARPON LH <i>Defect</i>	1	\$ 389.10	\$ 389.10
13	TAILGATE <i>Dented</i>	1	\$ 2,164.20	\$ 2,164.20
14	TAILGATE LOCK <i>new</i>	1	\$ 524.10	\$ 524.10
15	TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 399.10	\$ 399.10
16	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 734.80	\$ 734.80
17	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 78.10	\$ 78.10
18	VELLFIRE EMBLEM <i>new</i>	1	\$ 88.20	\$ 88.20

TOTAL PRICE: \$ 9,220.20
LESS 25% \$ 2,305.05
SUB TOTAL PRICE: \$ 6,915.15

5842.50

4381.87

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR BUMPER UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
3	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
5	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
6	TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00

TOTAL: \$ 220.00

170

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600	
3	WIRING CHECK	\$ 50.00	30	

4	TO APPLY TUFF COAT	\$ 150.00	60	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO REMOVE REAR CAMERA	\$ 100.00	50	
7	TO REMOVE REAR VIDEO RECORDER	\$ 100.00	50	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
9	TO REMOVE TAILGATE GLASS	\$ 180.00	120	

TOTAL: \$ 3,230.00

1820

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,135.15

TOTAL LABOUR COST: \$ 3,230.00

TOTAL REPAIR COST: \$ 10,365.15

total: 6371.87

2/s SK.
06 Days

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

SK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: