



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR23002853/Rwy3e2 Date: 14/04/2023 Code: SMR	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
	<b>Insured Veh.</b>	SMB 3605X	<b>Veh. Inspected</b>	SNA 2223P
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	BUS/03/23/5013	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	HUA YEN	<b>Assign Date</b>	20/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	PEUGEOT 308 SW	<b>c.c</b>	1199
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
	<b>Chassis No.</b>	VF3LRHNYWHS178482	<b>Colour</b>	WHITE
	<b>Odometer</b>	81490 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	225/45 R17	FALKEN	6 mm
	<b>L/H Front Tyre</b>	225/45 R17	FALKEN	6 mm
	<b>R/H Rear Tyre</b>	225/45 R17	FALKEN	6 mm
	<b>L/H Rear Tyre</b>	225/45 R17	FALKEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS			
<b>5. General Information</b>				
	<b>Accident Date</b>	11/03/2023	<b>Inspection Date</b>	20/03/2023
	<b>Survey held at</b>	J ONE CAR MOTOR 1 SOON LEE STREET, #05-22, PIONEER CENTRE, SINGAPORE 627605		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	