

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580

Our File No: CS/III23002854/SQY3E2**Date:** 25/07/2023**REFERENCE**

Insured/Claimant: TEOW CHENG ZHI KENNETH Policy No: D21MPC0003134-01
Date of Loss: 10/03/2023 Nature of Claim: OD Claim No: MPC2023D0002977

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA1736U**
Make & Model: MAZDA 3, 1.5 SEDAN (A) Engine No: P520517517
Reg. Date: 30/05/2018 (Man. Year: 2018) Chassis No: JM6BN22A8J0226155
Colour: Brown Odometer: 77929 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$69,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
Approved Total (Overridden) (S\$)		5,858.77		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	-600.00	5,258.77	-5,858.77	976.46
+ GST 8.00/8.00% (S\$)	0.00	420.70	-420.70	
Nett Amount (S\$)	-600.00	5,679.47	-6,279.47	1,046.58

INSPECTION

Date of Assignment: 20/03/2023
Date Inspected: 21/03/2023 Inspected At: Trans Eurokars Pte Ltd (Ubi)
5 Ubi Close
Singapore 408605
Estimated Period of Repair: 4.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2023)
Parts:	143	MAZDA 3 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA1736U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >