

Name & Address:

INDIA INTERNATIONAL INSURANCE P/L
64 CECIL STREET
#04-#05 IOB BUILDING
SINGAPORE 049711

Vehicle No:

SMA1736U

Date:

27-Mar-23

Brand & Model:

MAZDA 3

Franchise:

Mazda

Email/Fax No:

Contact No:

Chassis/VIN No:

JM6BN22A8J0226155

Contact Person (Eurokars)/Wip t

JESS / 43300

Type of Claim:

OWN DAMAGE

Policy No:

Date Of Registration:

30/05/2018

Contact No (Eurokars):

6331 0680
PARTS / MATERIAL CHARGES

K = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	UNIT PRICE	QTY	MARK	REVISED	PRICE
1	FRT BUMPER <i>Cra</i>	MB63B-50-031BBB	994.32	1		994.32	994.32 ✓
2	COVER RHF BUMPER BN <i>missing</i>	MB63B-50-101	44.17	1		44.17	44.17 ✓
3	COVER LHF BUMPER BN <i>missing</i>	MB63B-50-102	44.17	1		44.17	44.17 ✓
4	RETAINER(R), FRONT <i>Xnn</i>	MB63B-50-0T1B	15.77	1		-	15.77 ✓
5	RETAINER(L), FRONT <i>? BR</i>	MB63B-50-0U1A	15.77	1		-	15.77 ✓
6	REINFORCEMENT FRT BUMPER <i>? X nn</i>	MB61K-50-070A	576.77	1		-	576.77 ✓
7	STIFF FRT BUMPER <i>? X nn</i>	MBHNI-50-050B	94.57	1		-	94.57 ✓
8	BRACKET(L)FRT BN <i>? BR</i>	MB63B-50-164	12.98	1		-	12.98 ✓
9	BRACKET(R)FRT BN <i>Xnn</i>	MB63B-50-154	12.98	1		-	12.98 ✓
10	REINF.,RADIATOR GRIL BN <i>Cra</i>	MB63B-50-712B	163.43	1		163.43	163.43 ✓
11	CHROME RH <i>1 Scr</i>	MB63B-50-7J1A	231.12	1		-	231.12 ✓
12	CHROME LH <i>Cra</i>	MB63B-50-7K1A	231.12	1		231.12	231.12 ✓
13	PROTECTOR LHF BUMPER BN <i>Scr</i>	MB63E-50-B51B	24.87	1		24.87	24.87 ✓
14	PROTECTOR RHF BUMPER BN <i>Xnn</i>	MB63E-50-B41B	24.87	1		-	24.87 ✓
15	MASCOT,FRT BN/DK <i>me</i>	MD10J-51-730	74.18	1		74.18	74.18 ✓
16	LHF FENDER BM/BN <i>Bent X nn</i>	MB45A-52-211B	348.10	1		-	348.10 ✓
17	STAY LHF FENDER BM/BN <i>Bent</i>	MB45A-52-240	45.01	1		-	45.01 ✓
18	MUD GUARD LHF BM <i>Cut</i>	MB45A-56-140H	121.80	1		121.80	121.80 ✓
19	SHIELD(L),BN <i>? X nn</i>	MBHVI-56-115	22.85	1		-	22.85 ✓
20	FASTENER <i>me</i>	MB45A-56-146A	2.36	10		23.60	23.60 ✓
21	RUBBER(L),EDGE-F.FENDER <i>Xnn</i>	MB45A-56-916A	51.17	1		-	51.17 ✓
22	FASTENER <i>Xnn</i>	MGJ21-68-885B02	2.36	3		-	7.08 ✓
23	GRILLE TOP <i>Deform</i>	MB63B-50-033A53	377.94	1		377.94	377.94 ✓
24	RIVET <i>me</i>	MTK21-50-355	7.42	4		29.68	29.68 ✓
25	HEADLAMP LH BN <i>Cra</i>	MBABK-51-0LOE	1,228.05	1		1,228.05	1,228.05 ✓
26	RIVET <i>me</i>	MB092-51-833	2.95	1		2.95	2.95 ✓
27	LAMP(L),F.TURN BN <i>? X nn</i>	MB63C-51-360A	168.58	1		-	168.58 ✓
28	*** SUPPLEMENTARY ITEM ***						
29	BRACKET LH,FRT BUMPER <i>Cra</i>	MB63B-50-163	32.79	1		-	- ✓
30	BRACKET RH,FRT BUMPER <i>deform</i>	MB63B-50-153	32.79	1		-	- ✓
31	PLATE,SET <i>Cra</i>	MB63B-50-1C0A	178.61	1		-	- ✓
32	PLATE LH,SEAL <i>Cra</i>	MB63B-50-1V1	39.37	1		-	- ✓
33	HOLDER,LICENSE PLATE <i>Cra</i>	MBABD-50-170A	89.93	1		-	- ✓

34	FASTENER	<i>rec</i>	MB45A-56-146A	2.36	15	35.40	-	✓
35	GROMMET	<i>rec</i>	MGHP9-50-0Z5	2.36	2	4.72	-	✓

Sub-Total (Parts Price) 4,063.00 4,987.90

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE	
1	REPLACE FRT BUMPER. PO43300 / SUBLET 13004	660.00	1,500.00	660 ✓
2	SPRAY FRT BUMPER, LHF FENDER. PO43300 / SUBLET 13004	700.00	2,200.00	700 ✓
3	TO SUPPLY FRT NUMBER PLATE PO43300 / SUBLET 13004	70.00	70.00	missing ✓
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. PO43300 / SUBLET 13004	150.00	250.00	150 ✓
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. PO43300 / SUBLET 13004	180.00	300.00	180 ✓
6	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU).	-	250.00	250 ✓
7	SUNDRIES. PO43300 / SUBLET 13004	20.00	50.00	20 ✓

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Surveyor Remarks:

Sub-Total (Labour Price) 1,780.00 4,620.00

	REVISED	PRICE
Parts Price	4,063.00	4,987.90
Labour Price	1,780.00	4,620.00
Total (Initial Estimate)	5,843.00	9,607.90
Supp 1	-	-
Supp 2	-	-
Supp 3	-	-
Total (Before Excess)	5,843.00	9,607.90
Less Excess	-	-
TOTAL (After Excess)	5,843.00	9,607.90
GST 8%	467.44	768.63
GRAND TOTAL	6,310.44	10,376.53

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate. If you choose not to proceed with repair

4 days PIP/FFM g
21/3/23 11am
90097659

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: