

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO23002857/Uvy3m4	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	Date:	10/04/2023	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLD 4374G	Veh. Inspected	SLG 5958A	
	Policy No.	D22MTPV01007959	Coverage (\$)	0.00	
	Claim No.	CMTD2301121/RUC	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	20/03/2023	
2.	. Vehicle Particulars & Condition				
	Make & Model	TOYOTA WISH (A)	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	ZGE206029654	Colour	GREY	
	Odometer	425476 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/50 R17	WEST LAKE	6 mm	
	L/H Front Tyre	215/50 R17	WEST LAKE	6 mm	
	R/H Rear Tyre	215/50 R17	WEST LAKE	6 mm	
	L/H Rear Tyre	215/50 R17	WEST LAKE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/03/2023	Inspection Date	20/03/2023	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
	Estimate Days of Repair				
5b.		Lottillato			