



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打鳴呔，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date: 20/03/2023

ATTN: Motor Claim Department

Your Insured Vehicle - SKZ 796 U

Auto & General Insurance (Singapore) Pte Ltd
190 Clemenceau Ave #03-01 Singapore Shopping Centre
Singapore 239924
Tel: 62212199 Email: Claims@budgetdirect.com.sg

LKK Auto-Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Supplies are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK 67418434 YAM

Xin Yu.

Estimated Cost of repair for Vehicles Toyota Estime SKJ 323 K And SKZ 796 U on 16/03/2023 at 13:50.
To Supply:-

1pc	Rear Boot Cover	Deled		\$ 1,520.00	✓
1pc	Rear Boot Cover Inner Lock	Damaged		\$ 425.00	✓
1pc	Rear Boot Cover Logo	New		\$ 72.20	✓
1pc	Rear Boot Cover "AERAS PLATE"	Green		\$ 56.00	✓
1pc	Rear Boot Cover "ESTIMA PLATE"			\$ 47.00	✓
2pcs	Rear Boot Cover Lamp	RA am Ld	\$ 428.60	\$ 857.20	428.60
1pc	Rear Boot Cover Inner Rubber	Int		\$ 355.00	2
1pc	Rear Boot Cover Number Plate Garnish	am Ld		\$ 316.00	2
1pc	Rear Windscreen Glass Moulding	New		\$ 120.00	✓
1pc	Rear Lamp	New	\$ 607.00	\$ 1,214.00	+
1pc	Number Plate	New		\$ 65.00	+
1pc	Rear Panel	Deled	4874.80	\$ 817.00	625
1pc	Rear Panel Inner Garnish	Deled		\$ 275.00	✓
1pc	Rear Panel Inner Lock	New	3656.10	\$ 165.00	+
1pc	Rear Panel Inner Lock Cover	New		\$ 89.00	+
1pc	Rear Bumper	Deled		\$ 605.00	✓
1pc	Rear Bumper Side Retainer	New	\$ 65.00	\$ 130.00	+
1pc	Rear Bumper Reflector	New	\$ 75.00	\$ 150.00	+
1pc	Rear Bumper Clips	New	\$ 4.50	\$ 54.00	30
1pc	Antenna Electrical Assy	New		\$ 289.20	7
				\$ 7,621.60	
				less 20%	- \$ 1,524.32
				\$ 6,097.28	

1pc	Reverse Sensor	Damaged	360	\$ 380.00	s/n 300
1pc	Rear Windscreen Sealant	New		\$ 80.00	s/n 60

To dismantl & replace damage parts, panel beat where necessary
To putty, apply primer & spray paint on the affecte portion.
To remove rear windscreen
To remove reverse sensor.
To check wiring functions.

Adrian Ling
4/5 21/03/23
06 Days
\$ 800.00 700
\$ 850.00 700
\$ 120.00 ✓
\$ 80.00 50
\$ 80.00 30
\$ 8,487.28
Total: 5616.10
H/S: A.5K