



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23002860/Uvy3m4 Date: 20/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 7687L	Veh. Inspected	SLJ 3409R
Policy No.	D-22099587MFVS/26	Coverage (\$)	0.00
Claim No.	D23000948MFVS	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	20/03/2023
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3 SP (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6BN22A8H0120230	Colour	SILVER
Odometer	130473 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	CONTINENTAL	7 mm
L/H Front Tyre	205/60 R16	CONTINENTAL	7 mm
R/H Rear Tyre	205/60 R16	CONTINENTAL	7 mm
L/H Rear Tyre	205/60 R16	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/03/2023	Inspection Date	10/04/2023
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	