



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 5382D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT OF THE RHS REAR QUARTER PANEL.		300.00	200.00
	TO SPRAY PAINT RHS REAR QUARTER PANEL.		300.00	200.00
	TO SPRAY PAINT REAR BUMPER PARTIAL (NEAR QUARTER PANEL AREA).		500.00	200.00
	TO SPRAY RIM.		100.00	100.00
			1,200.00	700.00
	<b>GRAND TOTAL</b>		<b>1,200.00</b>	<b>700.00</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>			<b>700.00</b>

Report Ref No. CS/SMR23002861/Rny3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.