



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23002867/Uqy3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROAD SINGAPORE 438675		Date:	28/03/2023
ATTN: HAFIZUL FARHAN		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 1924A	Veh. Inspected	SLZ 2065X
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2023/017	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	20/03/2023
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN TOURAN (A)	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WVGZZZ1TZJW059853	Colour	BLACK
Odometer	145568 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R18	GOODYEAR	6 mm
L/H Front Tyre	225/45 R18	GOODYEAR	6 mm
R/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
L/H Rear Tyre	225/45 R18	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/03/2023	Inspection Date	21/03/2023
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	