



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MINISTRY OF DEFENCE DTTB FINANCIAL SERVICES CENTRE, DES, 5 DEPOT ROAD #15-01, DTT TOWER B. SINGAPORE 109684			Ref: CS/MIDA23002873/Rpq2 Date: 10/04/2023 Code: MIDA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	Veh. Inspected	SMY 1149M	
	Policy No. OR22016375 / 1	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	21/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MAZDA 3 5DR 1.5 AT M-HYBRID ASTINA	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JM6BP2HAAK1100948	Colour	GREY
	Odometer	28071 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/40Z R19	FALKEN	6 mm
	L/H Front Tyre	225/40Z R19	FALKEN	6 mm
	R/H Rear Tyre	225/40Z R19	FALKEN	6 mm
	L/H Rear Tyre	225/40Z R19	FALKEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE UNDERCARRIAGE. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	28/01/2023	Inspection Date	21/03/2023
	Survey held at	27A Tanjong Penjuru, Singapore 609042		
	Repairer	EUROKARS HABITAT PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	