

Name & Address:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Policy No:

Date:

Vehicle No:

SMY1149M

Brand & Model:

M3 M-HYBRID

Chassis/VIN No:

Date:

21-Mar-23

Franchise:

Mazda

Email/Fax No:

Type of Claim:

Date Of Registration:

18/02/2021

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT CROSSMEMBER <i>st</i>	MBDNF-34-80XC	1		-	\$ 2,567.26
2	FRONT LOWER ARM LH <i>lt</i>	MBCKE-34-350K	1		-	\$ 520.89
3	SIDE COVER RH CHASSIS FRONT <i>cm</i>	MBCJH-56-32ZA	1		-	\$ 45.69
4	SIDE COVER LH CHASSIS FRONT <i>cm</i>	MBCJH-56-34ZA	1		-	\$ 51.08
5	MUD GUARD LH FRONT <i>cm</i>	MBDEN-56-140	1		-	\$ 83.95
6	LOWER MUD GUARD LH FRONT <i>ms</i>	MBGAM-56-115	1		-	\$ 216.45
7	FASTENER <i>nr</i>	MB45A-56-146A	5		-	\$ 11.80
8	COVER UNDER CENTER <i>cm</i>	MDJJJ-56-111	1		-	\$ 198.92
9	COVER, SERVICE HOLE <i>nr</i>	MDJJJ-56-071	1		-	\$ 24.78
10	FRONT BUMPER <i>cm</i>	MBCKN-50-031DBB	1		-	\$ 994.32
11	TAPE SEAL <i>nr</i>	MBCKA-50-2G1A	2		-	\$ 17.04
12	TAPE SEAL <i>nr</i>	MBDWH-50-2G1	2		-	\$ 14.84
13	STIFF 'A' BUMPER FRONT <i>Xnr</i>	MBCKA-50-0S0B	1		-	\$ 87.32
14	TAPE, PROTECTOR <i>nr</i>	MBCKA-50-EM1	3		-	\$ 13.92
15	RETAINER S.S ULTRASONIC WITH TAPE. <i>nr</i>	MB0J8-67-UC6	2		-	\$ 53.78
16						\$ -

Sub-Total (Parts Price) \$ - \$ 4,902.04

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE FRONT BUMPER.	<i>660</i>	\$ 800.00
2	TO RESPRAY FRONT BUMPER.	<i>630</i>	\$ 700.00
3	TO REMOVE & REPLACE FRONT CROSSMEMBER & SUSPENSION FRONT LH.	<i>660</i>	\$ 1,500.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 560.00
5	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>? receipt X NN</i>	NETT	\$? 250.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>180</i>	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>200</i>	\$ 300.00
8	TO CARRY-OUT BODY CAVITY PRESERVATION, (INCLUDING NEW PARTS AND CAOUTCHOU).	<i>Xnr</i>	\$ 250.00
9	SUNDRIES.	<i>20</i>	\$ 50.00

Survey Date & Time:

21/03/23 @ 1030

Repair Days:

5 days

Excess:

Sub-Total (Labour Price) \$ - \$ 4,660.00

Surveyor Remarks:

Repair - up 90010068
Resey before repair

	REVISED	PRICE
Parts Price	\$ -	\$ 4,902.04
Labour Price	\$ -	\$ 4,660.00

SMY1149M OD BD ESTIMATE