

Motor Survey Report

Claim No :	<u>C10020152/JL</u>	Accident date:	<u>28.01.2023</u>	REPORT ON:	<u>16.02.2023</u>
Claim Type :	<u>OD</u>	Assign date :	<u>17.02.2023</u>		
Excess :	<u>\$600.00</u>	Survey date :	<u>17.02.2023</u>	<u>11AM</u>	
Insured's vehicle:	<u>SMY1149M</u>	Resurvey :	<u>24.03.2023</u>	<u>WS</u>	
Repairer :	<u>EUROKARS GROUP</u> LIM TENG KIAT				
Vehicle No :	<u>SMY1149M</u>				
Make & Model :	<u>MAZDA 3 5DR 1.5 AT M-HYBRID ASTINA</u>				
Chassis / VIN :	<u>JM6BP2HAAK1100948</u>	Odometer :	<u>28,072</u>	<u>KM</u>	
Engine number :	<u>P520615202</u>	Color/s :	<u>Grey</u>		
Capacity (cc) :	<u>1,496</u>	<u>88.0 kW (118 bhp)</u>	Registration:	<u>18/2/2021</u>	<u>TO 17/2/2031</u>
General Condition:	<u>GOOD</u>	<u>stationary check</u>			
Steering :	<u>NOT AFFECTED</u>	Brakes :	<u>NOT AFFECTED</u>		
Tyre Specification:	<u>225/40/R19 FALKEN SPORTS RIMS</u>				
Front Lh :	<u>6</u> mm	Front Rh :	<u>6</u> mm		
Rear Lh :	<u>6</u> mm	Rear Rh :	<u>6</u> mm		



MOTORCAR

EXCEED 14 DAYS. PENDING VERIFICATION
AUTHORISE ON 20.02.2023 , 1PM.

Description of damage: FRONT UNDERCARRIAGE DAMAGED. CROSSMEMBER, ENGINE AND CHASSIS COVERING, BUMPER , ETC.

TOWING RECOVERY:\$ 85

Market Value	\$	<u>109,791.00</u>
LTA Rebate	\$	<u>45,743.00</u>
Economic limit	\$	<u>64,048.00</u>



Repair estimate \$ 9,990.24

Finalise amount \$ 8,222.92 before GST

After Excess \$ 7,622.92

Repair work days : 5

Remarks:

Surveyed by : DERRICK QUOK 

Date of report : 13.04.2023

Name & Address:

BUDGET DIRECT INSURANCE

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore 239924

Vehicle No:

SMY1149M

Brand & Model:

M3 M-HYBRID

Date:

24-Mar-23

Franchise:

Mazda

E-mail/Fax No:

Contact No:

Chassis/VIN No:

JM6BP2HAAK1100948

Contact Person (Eurokars)/Wip No:

LIM / 55305

Type of Claim:

OWN DAMAGE

Policy No:

Date Of Registration:

18/02/2021

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES				MARK = Survey Marking [Key "A" if item is approved]			
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE	
1	UNDER COVER FRONT <i>✓ torn Big □</i>	MBCKA-56-11YF	1	✓	-	\$	228.76 ✓
2	LOWER MUD GUARD RH FRONT <i>✓ torn Small △</i>	MBDMT-56-13Y	1	✓	-	\$	147.50 ✓
3	RIVET <i>✓ New</i>	MTK21-50-355	7	✓	-	\$	51.94 ✓
4						\$	-

Sub-Total (Parts Price) \$ - \$ 428.20

LABOUR / SERVICES CHARGES				REVISED		PRICE	
NO	DESCRIPTION						

Survey Date & Time:

Repair Days:

Sub-Total (Labour Price) \$ - \$ -

Surveyor Remarks:

Parts Price \$ - \$ 428.20

Labour Price \$ - \$ -

Total (Supp 1) \$ - \$ 428.20

Name & Address:

BUDGET DIRECT INSURANCE
190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore 239924

Vehicle No:

SMY1149M

Date:

17-Feb-23

Brand & Model:

M3 M-HYBRID

Franchise:

Mazda

Email/Fax No:

17.2.27/
11am

Contact No:

96927571

Chassis/VIN No:

JM6BP2HAAK1100948

LIM / 55305

Type of Claim:

OWN DAMAGE

Policy No:

Authorise 20.2.23, 1pm.

Date Of Registration:

18/02/2021

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES				MARK = Survey Marking [Key "A" if item is approved]		
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT CROSSMEMBER ✓ Dent	MBDNF-34-80XC	1	✓	-	\$ 2,567.26 ✓
2	FRONT LOWER ARM LH ✓ Bent	MBCKE-34-350K	1	✓	-	\$ 520.89 ✓
3	SIDE COVER RH CHASSIS FRONT ✓ torn	MBCJH-56-32ZA	1	✓	-	\$ 45.69 ✓
4	SIDE COVER LH CHASSIS FRONT ✓ torn	MBCJH-56-34ZA	1	✓	-	\$ 51.08 ✓
5	MUD GUARD LH FRONT ✓ splash shield ✓ torn	MBDEN-56-140	1	✓	-	\$ 83.95 ✓
6	LOWER MUD GUARD LH FRONT ✓ missing torn	MBGAM-56-115	1	✓	-	\$ 216.45 ✓
7	FASTENER ✓ N/A	MB45A-56-146A	5	✓	-	\$ 11.80 ✓
8	COVER UNDER CENTER ✓ torn	MDJJJ-56-111	1	✓	-	\$ 198.92 ✓
9	COVER, SERVICE HOLE ✓ Bent	MDJJJ-56-071	1	✓	-	\$ 24.78 ✓
10	FRONT BUMPER ✓ torn	MBCKN-50-031DBB	1	✓	-	\$ 994.32 ✓
11	TAPE SEAL ✓ N/A for bumper	MBCKA-50-2G1A	2	✓	-	\$ 17.04 ✓
12	TAPE SEAL ✓ N/A	MBDWH-50-2G1	2	✓	-	\$ 14.84 ✓
13	STIFF 'A' BUMPER FRONT ? X	MBCKA-50-0S0B	1	?	X	\$ 87.32 X
14	TAPE, PROTECTOR ✓ N/A	MBCKA-50-EM1	3	✓	-	\$ 13.92 ✓
15	RETAINER S.S ULTRASONIC WITH TAPE. ✓ N/A for sensors	MB0J8-67-UC6	2	✓	-	\$ 53.78 ✓
16						\$ -

Sub-Total (Parts Price) \$ - \$ 4,902.04

LABOUR / SERVICES CHARGES			
NO	DESCRIPTION	REVISED	PRICE
1	TO REPLACE FRONT BUMPER.	660	\$ 800.00
2	TO RESPRAY FRONT BUMPER.	630	\$ 700.00
3	TO REMOVE & REPLACE FRONT CROSSMEMBER & SUSPENSION FRONT LH.	660	\$ 1,500.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	✓ NETT	\$ 560.00
5	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	X NETT	\$ 250.00 X
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	200	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250	\$ 300.00
8	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU).	X	\$ 250.00 X
9	SUNDRIES.	S/N 20	\$ 50.00

Survey Date & Time:	Repair Days:	Excess:
---------------------	--------------	---------

Sub-Total (Labour Price) \$ - \$ 4,660.00

Surveyor Remarks:

	REVISED	PRICE
Parts Price	\$ -	\$ 4,902.04
Labour Price	\$ -	\$ 4,660.00

REPAIR ESTIMATE

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- A fee of \$400 (excl. GST) will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Total (Initial Estimate)	\$	-	\$	9,562.04
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	9,562.04
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	9,562.04
GST	8%	\$	-	\$ 764.96
GRAND TOTAL		\$	-	\$ 10,327.00

PARTS = \$5,242.92
 S/Nett = \$20.00
 Labour = \$2,960.00
Total = \$8,222.92

FINALISE WITH LEE YAO QUAN
 12.04.2023