



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JRL 1281

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR	DISTORTED	115.00	115.00
1	HANDLE BAR Y BRACKET	BENT	135.00	135.00
1	SET HANDLE GRIP	TORN	30.00	30.00
1	SET BALANCER NIPPLE	MISSING	18.00	18.00
1	FRONT BRAKE LEVER	TO REPAIR SEE LABOUR	29.00	-
1	SET MIRROR	MISSING	50.00	50.00
2	FRONT SIGNAL ASSY (LH/RH) @\$55.00	SERVICEABLE	110.00	-
1	FRONT SPOILER	DISTORTED	42.00	42.00
1	FRONT SHIELD	CRACKED	270.00	195.00
1	FRONT FENDER	DISTORTED	122.00	122.00
2	FRONT FORK ASSY (LH/RH) @\$320.00	BENT	640.00	530.00
1	STEERING CONE WITH BEARING	NECESSARY	195.00	125.00
1	FRONT MUDGUARD	CRACKED	75.00	75.00
1	TAIL LAMP ASSY	CRACKED	95.00	95.00
1	FRONT BRAKE DISC ROTOR	WARPED	285.00	285.00
1	GEAR PEDAL	BENT	90.00	90.00
2	REAR SIDE PANEL (LH/RH) @\$78.00	CRACKED	156.00	156.00
2	LEG SHIELD INNER COVER (LH/RH) @\$42.00	DISTORTED	84.00	84.00
2	LOWER SIDE COVER (LH/RH) @\$50.00	SERVICEABLE	100.00	-
1	FOOT REST BAR WITH RUBBER	BENT	95.00	95.00
1	REAR FENDER	CRACKED	85.00	85.00
1	REAR SHIELD	CRACKED	85.00	85.00
	LESS 10% DISCOUNT		-290.60	-241.20
			2,615.40	2,170.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET SPORT RIM (SN)	BENT	350.00	350.00
1	FRONT WHEEL AXLE (SN)	BENT	35.00	35.00
1	SET NUMBER PLATE (SN)	BENT	40.00	40.00
1	GIVI BOX (SN)	DENTED/CUT	280.00	280.00

Report Ref No. CS/TP23002888/Kny3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GIVI BOX BRACKET (SN) <u>LABOUR</u> STRAIGHTEN CHASSIS FRAME. LABOUR TO DISMANTLE AND FIX PARTS. INCLUSIVE OF THE REPAIR OF FRONT BRAKE LEVER. TOWING CHARGE.	BENT	150.00	150.00
			855.00	855.00
			350.00	120.00
			380.00	150.00
			60.00	30.00
		790.00	300.00	
GRAND TOTAL			4,260.40	3,325.80
RECOMMENDED COST OF REPAIRS				3,325.80

Report Ref No. CS/TP23002888/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.