



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 7 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



Reference No.: 180323

Date: 18.03.2023

Tan Boon Chye
37 Hougang Ave 7 #05-03
Singapore 538803.

Mercedes Benz S350

Estimate Repair Cost for Vehicle Reg. No: SNH 5988 J

1 Pc. Front Bonnet	HN		1,991.00 (Nett)	X
1 Pcs. Front Bonnet Lock	St Catch	@ 105.00	210.00 (Nett)	✓
2 Pcs. Front Bonnet Lock Catch	HN	@ 95.00	190.00 (Nett)	X
2 Pcs. Front Bonnet Spring Stopper	HN	@ 82.00	164.00 (Nett)	X
1 Pc. Front Bonnet Logo	HN		110.00 (Nett)	X
10 Pcs. Front Bonnet Heat Seal Clips	HN	@ 6.00	60.00 (Nett)	X
1 Pc. Front Grille Assy.	ORALC		991.00 (Nett)	✓
1 Pc. Front Grille Logo	HP		95.00 (Nett)	X
2 Pcs. Front Head Lamp Assy.	W/S ORALC/SHH	@ 2,990.00	5,980.00 (Nett)	✓
2 Pcs. Front Head Lamp Panel	HN	@ 398.00	796.00 (Nett)	X
1 Pc. Front Centre Panel	HN		290.00 (Nett)	X
1 Pc. Front Bumper	distona / ORALC		2,038.00 (Nett)	✓
1 Pc. Front Bumper Sponge	HN		499.00 (Nett)	✓
1 Pc. Front Bumper Centre Inner Garnish	ORALC		299.00 (Nett)	✓
2 Pcs. Front Bumper Corner Garnish	HN	@ 315.00	630.00 (Nett)	X
2 Pcs. Front Bumper Side Retainer	HN	@ 298.50	597.00 (Nett)	X
2 Pcs. Front Bumper Side Holder	ORALC	@ 199.00	398.00 (Nett)	✓
1 Pc. Front Bumper Centre Lower Garnish	HN		299.00 (Nett)	X
1 Pc. Front Bumper Centre Grille	HN		285.00 (Nett)	X
2 Pcs. Front Bumper Day Light	HN	@ 490.00	980.00 (Nett)	X
2 Pcs. Front Bumper Fog Lamp Garnish	HN	@ 190.00	380.00 (Nett)	X
1 Pc. Front Bumper Reinforcement	HN		599.00 (Nett)	X
10 Pcs. Front Bumper Clips	HN	@ 6.00	60.00 (Nett)	30/-
10 Pcs. Front Bumper Rivet	HN	@ 8.00	80.00 (Nett)	X
2 Pcs. Front Bumper Grille Base	HN	@ 190.00	380.00 (Nett)	X
6 Pcs. Front Parking Sensor	2pc Dam 4pc HN	@ 328.00	1,968.00 (Nett)	✓
6 Pcs. Front Parking Sensor Holder	2pc HN 4pc	@ 59.00	354.00 (Nett)	✓
6 Pcs. Front Parking Sensor Ring	2pc HN 4pc	@ 28.00	168.00 (Nett)	✓
1 Pc. Front Parking Sensor Harness Wire	HN		498.00 (Nett)	X
1 Pc. No. Plate & Box	✓		60.00 (S. Nett)	45/-



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



1 Pc. Rear Boot <i>bt</i>	1,990.00 (Nett) ✓
1 Pc. Rear Boot C&C Plate <i>hw</i>	45.00 (Nett) ✓
1 Pc. Rear Boot Lock <i>Dome</i>	299.00 (Nett) ✓
1 Pc. Rear Boot Catch <i>hw</i>	238.00 (Nett) X
1 Pc. Rear Boot Chrome <i>hw</i>	391.00 (Nett) X
1 Pc. Rear Boot S350L Emblem <i>hw</i>	126.00 (Nett) ✓
1 Pc. Rear Boot Logo <i>hw</i>	128.00 (Nett) ✓
1 Pc. Rear Boot AMG Emblem <i>hw</i>	139.00 (Nett) ✓
2 Pcs. Rear Lamp Assy. <i>o/s hw w/s mounty @ 1,280.00</i>	2,560.00 (Nett) ✓
1 Pc. Rear End Panel <i>hw</i>	688.00 (Nett) X
1 Pc. Rear End Panel Lock Garnish <i>hw</i>	391.00 (Nett) X
1 Pc. Rear Bumper <i>distorted</i>	1,990.00 (Nett) ✓
1 Pc. Rear Bumper Centre Holder <i>broken</i>	298.00 (Nett) ✓
2 Pcs. Rear Bumper Side Retainer <i>o/s hw w/s @ 205.00</i>	410.00 (Nett) ✓
2 Pcs. Rear Bumper Side Garnish <i>hw @ 190.00</i>	380.00 (Nett) X
1 Pc. Rear Bumper Lower Pad <i>warranty broken</i>	699.00 (Nett) ✓
2 Pcs. Rear Bumper Exhaust Garnish <i>hw @ 254.00</i>	508.00 (Nett) X
2 Pcs. Rear Bumper Exhaust Aluminum Cover <i>hw @ 210.00</i>	420.00 (Nett) X
1 Pc. Rear Bumper Reinforcement <i>bt</i>	990.00 (Nett) ✓
1 Pc. Rear Bumper Sponge <i>HF</i>	391.00 (Nett) X
6 Pcs. Rear Parking Sensor <i>2pc Dome 2pc hw @ 298.00</i>	1,788.00 (Nett) ✓
6 Pcs. Rear Parking Sensor Holder <i>2pc hw 2pc hw @ 68.00</i>	408.00 (Nett) ✓
6 Pcs. Rear Parking Sensor Ring <i>2pc hw 2pc hw @ 25.00</i>	150.00 (Nett) ✓
1 Pc. Rear Lower Spare Tyre Garnish <i>bt</i>	399.00 (Nett) ✓
1 Pc. Rear Exhaust <i>vt</i>	3,910.00 (Nett) ✓
2 Pcs. Rear Exhaust Chrome (AMG) <i>o/s bt w/s hw @ 691.00</i>	1,382.00 (Nett) ✓
2 Pcs. Rear Lamp Inner Garnish <i>broken @ 135.10</i>	270.20 (Nett) ✓
4 Pcs. Rear Exhaust Mounting <i>hw @ 60.00</i>	240.00 (Nett) <i>X 1pc</i>
1 Pc. Spare Tyre Board <i>hw</i>	590.00 (Nett) X
1 Pc. Weather Slips <i>defunct</i>	391.00 (Nett) ✓

Total (Panels / Parts): 44,058.20 (SGD)

LABOR CHARGES

To check wiring, remove & refit all wires.

~~200.00~~ 30/-

To remove & refit radiator & air-con condenser & top-up Gas & oil.

280.00 *hw*



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



To remove & refit interior garnish, carpet & all accident Affected area.	250.00 120/-
To remove & refit exhaust system.	280.00 80/-
To welding, knocking, straightening repair & renew all Accident affected damage parts.	2,000.00 1000/-
To respray painting on all accident inner & outer Affected area.	2,000.00 1000/-
To rust proof all accident affected damaged area.	200.00 40/-
To diagnostic & check control unit, reset memory to Identification standard.	380.00 150/-

Total (Labor Charges): 5,590.00 (SGD)

TOTAL COST SUMMARY

PANELS / PARTS
LABOR CHARGES

22/03/2023 @ 1000m
 Not Actual
 2/sum 9 days.
 Check part prices.
 44,058.20
 5,590.00
 Jn
 2kk Adv

Grand Total: 49,648.20 (SGD)

We shall be glad if you can forward the payment at your early convenience.

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah


Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com



Payment Method

1. PAYNOW via UEN 39108900E
2. Bank Wire Transfer - (SGD Account)

Beneficiary/Company Name	Alfred Auto Services & Supplies
UEN no.	39108900E
Beneficiary's Bank Name	OCBC Bank
Account No.	620-453233-001
Bank Code	7339
Branch Code	620
Swift Code	OCBCSGSG