

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SMH1451D

Make & Model: Mitsubishi Lancer

Chassis number: JMYSRCY1AFU001551

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper RH side retainer X	1	\$ 44.00
2	Front bumper LH side retainer X	1	\$ 44.00
3	RH headlamp upper panel X	1	\$ 89.00
4	RH headlamp assy SCR	1	\$ 702.00
5	RH headlamp lock clips X	1set	\$ 22.00
6	LH headlamp upper panel X	1	\$ 89.00
7	LH headlamp assy X	1	\$ 702.00
8	LH headlamp lock clips X	1set	\$ 22.00
9	Front RH fender SCR R	1	\$ 489.00
10	Front RH fender splash shield BR	1	\$ 109.00
11	Front RH fender splash shield clips MCL	1set	\$ 60.00
12	Front RH wheel bearing X	1	\$ 185.00
13	Front RH shock absorber X	1	\$ 389.00
14	Front RH knuckle arm X	1	\$ 532.00
15	Front RH lower arm X	1	\$ 348.00
16	Front RH tie rod end X	1	\$ 78.00

\$ 3,904.00

Parts less 10% \$ 390.40

Total \$ 3,513.60

No.	Special Nett Items	Qty	Amount S\$
1	Front bumper (after market) B	1	\$ 1,050.00
2	Front bumper upper wire mesh X	1	\$ 280.00
3	Front bumper lower wire mesh X	1	\$ 450.00
4	Front bumper RH side wire mesh X	1	\$ 120.00
5	Front bumper LH side wire mesh X	1	\$ 120.00
6	Front bumper clips MCL	1set	\$ 80.00
7	Front bumper rivets X	1set	\$ 60.00
8	Front number plate X	1	\$ 80.00
9	Bonnet (after market) X	1	\$ 1,600.00
10	Front RH sport rim SCR	1	\$ 1,350.00
11	Front RH tyre X	1	\$ 480.00
12	Front RH tyre white wording X	1	\$ 150.00

Total: \$ 5,820.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall	\$ 1,200.00

400

	damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas		
2	Spray painting on affected areas and panels	\$	1,000.00
3	Check wiring and lighting system on affected areas	\$	80.00
4	Apply rust coating chemical on affected areas and panels	\$	70.00
5	Refocus and adjust headlamps assy	\$	80.00
6	Test drive and adjust wheel alignment system	\$	180.00
7	Remove and replace front undercarriage parts to assist repair	\$	480.00

400

30

X

X

X

X

Total: \$ 3,090.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 3,513.60

Special Nett: \$ 5,820.00

Labour: \$ 3,090.00

Total Amount: \$ 12,423.60

32m/s L/S

21/3/23

1st m /