

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584
Company Reg No: 201929175W

Vehicle number: SMH1451D
Make & Model: Mitsubishi Lancer
Chassis number: JMYSRCY1AFU001551

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Contacts:

831
-10%
747.90

900 ✓

30 ✓

500 ✓

1430

400

	damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas		
2	Spray painting on affected areas and panels	\$	1,000.00
3	Check wiring and lighting system on affected areas	\$	80.00
4	Apply rust coating chemical on affected areas and panels	\$	70.00
5	Refocus and adjust headlamps assy	\$	80.00
6	Test drive and adjust wheel alignment system	\$	180.00
7	Remove and replace front undercarriage parts to assist repair	\$	480.00

Total: \$ 3,090.00 830

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 3,513.60
Special Nett: \$ 5,820.00
Labour: \$ 3,090.00

Total Amount: \$ 12,423.60

32yrs
L/S
21/3/23
1rkm

3007.90

L/S - 2406.32
= 2400