

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation

DATE : 28.03.2023
 VEH NO : SLC8237Z
 MODEL : Suzuki Vitara
 D O A : 19.03.2023
 YR REF : GBB5608E

Xiao Tony

TSMLYE21800220675

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8237Z (SUZUKI VITARA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Number Plate Lamp <i>xtc new</i>	2	116.40 <i>x</i>
2	Rear Bumper <i>Dehnd.</i>	1	971.40 <i>✓</i>
3	Rear Bumper Side Holder - LH & RH <i>xtc new</i>	2	76.80 <i>x</i>
4	Rear Bumper Reflector - LH & RH <i>LH & RH</i>	2	91.20 <i>45.60</i>
5	Rear Bumper Lower Diffuser <i>Dehnd</i>	1	357.60 <i>✓</i>
6	Rear Bumper Lower Grille <i>Dehnd</i>	1	85.20 <i>✓</i>
7	Rear Bumper Reinforcement <i>Dehnd.</i>	1	298.60 <i>✓</i>
8	Rear Bumper Top Garnish <i>xtc</i>	1	175.60 <i>✓</i>
9	Rear Bumper Centre Garnish <i>xtc new</i>	1	66.70 <i>x</i>
10	Reverse Sensor <i>2 pieces dnd</i>	4	621.60 <i>310.80</i>
11	Reverse Sensor Holder <i>xtc</i>	4	100.00 <i>✓</i>
12	Rear End Panel <i>Dehnd</i>	1	497.30 <i>✓</i>
13	Rear End Panel Top Garnish <i>Dehnd</i>	1	197.40 <i>✓</i>
14	Rear End Panel Air Vent <i>xtc new</i>	2	101.80 <i>x</i>
15	Rear End Panel Antenna Sensor <i>dnd</i>	1	162.90 <i>✓</i>
16	Taillamp - LH & RH <i>xtc new</i>	2	761.00 <i>x</i>
17	Tailgate <i>Dehnd</i>	1	1,155.80 <i>✓</i>
18	Tailgate Lock <i>dnd.</i>	1	223.80 <i>✓</i>
19	Tailgate Weatherstripe <i>xtc new</i>	1	194.90 <i>x</i>
20	Tailgate Outer Garnish <i>xtc new</i>	1	373.70 <i>✓</i>
21	Tailgate Outer Garnish Opener Sensor <i>xtc new</i>	1	137.10 <i>x</i>
22	Tailgate Outer Garnish Opener Switch <i>xtc new</i>	1	136.20 <i>x</i>
23	Tailgate Reflector - LH & RH <i>xtc new</i>	2	669.60 <i>✓</i>
24	Tailgate Pull Pocket <i>xtc new</i>	1	25.40 <i>x</i>
25	Tailgate Inner Trimboard <i>xtc new</i>	1	398.90 <i>✓</i>
26	Tailgate Glass Moulding <i>xtc new</i>	1	90.50 <i>✓</i>
27	Tailgate Wiper Motor <i>xtc new</i>	1	388.90 <i>x</i>
28	Suzuki Logo <i>xtc new</i>	1	45.90 <i>✓</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8237Z (SUZUKI VITARA)

29	Suzuki Wording	1	44.10	✓
30	Vitara Wording	1	55.90	✓
31	All Grip Emblem	1	49.40	✓
32	Rear Fender Inner Trimboard	1	876.80	+
33	Spare Tyre Panel	1	1,008.50	+
34	Spare Tyre Panel Top Board	1	209.60	✓
35	Rear Exhaust Pipe	1	629.40	+
36	Rear Exhaust Pipe Mounting	1	38.40	+
37	Rear Exhaust Pipe Gasket	1	35.10	+
38	Rear Exhaust Pipe Heat Shield	1	124.30	+
			11,593.70	
Less 15%			(1,739.06)	
			\$ 9,854.65	

S/NETT ITEMS

1	Rear Number Plate	1	\$ 30.00	✓
2	Rear Number Plate Holder	1	\$ 30.00	✓
3	Rear Bumper Clips	1 set	\$ 30.00	✓
4	Rear End Panel Top Garnish Clips	1 set	\$ 20.00	✓
5	Rear End Panel Sealant	1	\$ 60.00	✓
6	Tailgate Outer Garnish Clips	1 set	\$ 20.00	✓
7	Tailgate Inner Trimboard Clips	1 set	\$ 30.00	✓
8	Tailgate Glass Sealant	1	\$ 60.00	✓
9	Rear Camera	1 set	\$ 480.00	+
Total Parts			\$ 10,614.65	

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 1,600.00	80
2	To putty & spray up paint works	\$ 1,400.00	80
3	To check wiring	\$ 50.00	30
4	To remove reverse sensor	\$ 100.00	50
5	To remove rear camera	\$ 100.00	+
6	To remove upholstery & rear seat	\$ 100.00	80
7	To transfer tailgate fittings	\$ 280.00	80
8	To remove tailgate fittings	\$ 150.00	50
9	To remove tailgate glass	\$ 180.00	120

RE : ESTIMATE FOR ACCIDENT REPAIR SLC8237Z (SUZUKI VITARA)

10 To remove exhaust pipe

2110

\$ 150.00

x.

Total Labour

\$ 4,110.00

Grand Total

\$ 14,724.65

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Admin Lj

L/s 06 Days.

total: 8931.66

L/s: 6350

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: