

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



Ezyng

DATE : 20.03.2023

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNB120K**
MODEL : **FERRARI 458 ITALIA**
DATE OF ACCIDENT : 17.03.2023
TIME OF ACCIDENT : 15:45 HOURS

2FF67NH C000176677

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 21,855.00	\$ 21,855.00
2	REAR BUMPER SIDE GRILLE (UPPER) <i>Dented LH</i>	2	\$ 972.35	\$ 1,944.70
3	REAR BUMPER SIDE GRILLE (LOWER) <i>Dented LH</i>	2	\$ 368.20	\$ 736.40
4	REAR NUMBER PLATE LAMP <i>Not new</i>	2	\$ 89.40	\$ 178.80
5	REAR BUMPER LOWER DIFFUSER <i>Cracked</i>	2	\$ 1,956.00	\$ 3,912.00
6	REAR BUMPER LAMP <i>LH cracked</i>	2	\$ 1,869.40	\$ 3,738.80
7	REAR BUMPER LOGO <i>New</i>	1	\$ 286.40	\$ 286.40
8	REAR BUMPER LAMP GARNISH <i>LH cracked</i>	2	\$ 357.90	\$ 715.80
9	REAR BUMPER SENSOR <i>2 pieces dented</i>	3	\$ 482.40	\$ 1,447.20
10	REAR BUMPER SENSOR HOLDER <i>New</i>	4	\$ 60.85	\$ 243.40
11	REAR BUMPER SENSOR WIRE HARNESS <i>Not new</i>	1	\$ 952.30	\$ 952.30
12	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 4,662.00	\$ 4,662.00
13	REAR BUMPER CENTER BRACKET <i>Not new</i>	1	\$ 953.20	\$ 953.20
14	REAR EXHAUST CHROME PIPE <i>Not new</i>	1	\$ 1,356.00	\$ 1,356.00
15	REAR EXHAUST BOX <i>Not new</i>	1	\$ 4,967.20	\$ 4,967.20
16	REAR EXHAUST MOUNTING <i>3 AHF</i>	4	\$ 98.60	\$ 394.40
17	REAR EXHAUST GASKET <i>New</i>	1	\$ 168.20	\$ 168.20
18	REAR EXHAUST INSULATOR <i>LH Dented</i>	2	\$ 588.20	\$ 1,176.40
19	REAR FENDER COWLING <i>Not new</i>	2	\$ 365.40	\$ 730.80
20	TAIL LAMP LH <i>Cracked</i>	1	\$ 1,932.00	\$ 1,932.00
21	REAR OIL COOLER LH <i>Not new</i>	1	\$ 2,463.00	\$ 2,463.00

11900
972.35
368.20
1556.
1869.40
357.90
964.80
588.20

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNB120K**
 MODEL : **FERRARI 458 ITALIA**
 DATE OF ACCIDENT : 17.03.2023
 TIME OF ACCIDENT : 15:45 HOURS

22	REAR OIL COOLER AIR GUARD LH <i>cracked</i>	1	\$ 358.60	\$ 358.60	✓
23	REAR OIL COOLER FAN C/W MOTOR LH <i>new</i>	1	\$ 1,679.20	\$ 1,679.20	+
24	REAR OIL COOLER SIDE AIR GUARD LH <i>new</i>	1	\$ 168.00	\$ 168.00	+
25	REAR OIL COOLER BRACKET <i>new</i>	2	\$ 164.00	\$ 328.00	+

26459.85

2381332

TOTAL PRICE \$ 57,347.80
 LESS 10% \$ 5,734.78
 SUB TOTAL PRICE \$ 51,613.02

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 200.00	\$ 200.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	✓
3	ENGINE OIL <i>new</i>	1	\$ 850.00	\$ 850.00	+
4	REAR SPOILER (CARBON FIBER) <i>cracked</i>	1	\$ 4,500.00	\$ 4,500.00	3600

3660

TOTAL \$ 5,610.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 2,400.00	<i>800</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>50</i>
4	WIRING AND BULB CHECK	\$ 250.00	<i>50</i>
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 350.00	<i>80</i>
6	REMOVE AND REFIX REAR OIL COOLER	\$ 280.00	<i>X</i>

TO : **ALLIANZ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNB120K**
MODEL : **FERRARI 458 ITALIA**
DATE OF ACCIDENT : 17.03.2023
TIME OF ACCIDENT : 15:45 HOURS

7	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 380.00	x
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 1,200.00	300

TOTAL \$ **6,910.00**

ESTIMATE REPORT

TOTAL PARTS COST : \$ 57,223.02
TOTAL LABOUR COST : \$ 6,910.00
TOTAL REPAIR COST : \$ 64,133.02

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRNE

HP : 8297 9787

Adrian King.
1/3 21/03/23.
06 Days.

total: 29353.32
2/s: 23.4K

23.4K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: