

KFS Motor

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
VEHICLE NO. : SLQ7037S
ACCIDENT DATE : 18-03-2023 12:30
THIRD PARTY REF. : FBT3773D

INVOICE NO : TEST

DATE : 26-04-2023

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEHICLE SLQ7037S TOYOTA AQUA HYBRID 1.5S CVT

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	FRONT DOOR RH	440.00
1	FRONT DOOR FAME STICKER	28.00
1	FRONT DOOR RUN CHANNEL RH	70.00
1	FRONT DOOR SIDE MIRROR RH	265.00
1	FRONT DOOR SIDE MIRROR COVER RH	40.00
1	REAR DOOR RH	400.00
1	REAR DOOR FAME STICKER RH	25.00
1	REAR DOOR GLASS RH	220.00
1	REAR DOOR OUTER MOULDING	35.00
1	REAR FENDER RH	480.00
1	REAR DOOR RUN CHANNEL RH	60.00
1	REAR BUMPER SIDE RETAINER RH	36.00*
		2,099.00
ADD 10 %		209.90
TOTAL (A)		2,308.90

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	TO REMOVE/REFIT REAR FENDER INNER GARNISH RH	50.00
1	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	80.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FI- TTING NEW PARTS	600.00

VEHICLE NO. : SLQ7037S
ACCIDENT DATE : 18-03-2023 12:30
THIRD PARTY REF. : FBT3773D

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	SPRAYPAINTING CHARGES	860.00
TOTAL (D)		<u>1,620.00</u>
TOTAL REPAIR COST :		<u>3,928.90</u>
G S T % :		274.31
EXCESS AMOUNT :		500.00
INVOICE AMOUNT :		<u>3,703.21</u>

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 Mar 2023)
Parts: N/A TOYOTA AQUA 1.5 E 1.5 SA (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SLQ7037S/21/03/2023 11:20
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER RH	0.00	0.00	490.00 F Sci
2	10		*FRONT FENDER SHIELD CLIP	0.00	0.00	25.00 F X
3	1		*FRONT DOOR RH	0.00	0.00	440 680.00 F DT
4	1		*FRONT DOOR FAME STICKER RH	0.00	0.00	— *28.00 F ?
5	1		*FRONT DOOR OUTER MOULDING RH	0.00	0.00	— *120.00 F ?
6	1		*FRONT DOOR RUN CHANNEL RH	0.00	0.00	— *70.00 F ?
7	1		*FRONT DOOR SIDE MIRROR RH	0.00	0.00	— *265.00 F WISS
8	1		*FRONT DOOR SIDE MIRROR COVER RH	0.00	0.00	— *40.00 F WISS
9	1		*REAR DOOR RH	0.00	0.00	— *400.00 F Sci
10	1		*REAR DOOR FAME STICKER RH	0.00	0.00	— *25.00 F ?
11	1		*REAR DOOR GLASS RH	0.00	0.00	220 *250.00 F Sci
12	1		*REAR DOOR OUTER MOULDING RH	0.00	0.00	— *35.00 F ?
13	1		*REAR DOOR RUN CHANNEL RH	0.00	0.00	60 *85.00 F ?
14	1		*REAR FENDER RH	0.00	0.00	— *480.00 F DT
15	1		*REAR LAMP RH	0.00	0.00	— *485.00 F X

F=Franchise part.

Sub Total (\$\$)	2,878.00
+ Margin on L,N Items 10.00% (\$\$)	287.80
Total Parts (\$\$)	3,165.80

Kan Fook Sing Motor Workshop/SLQ7037S/21/03/2023 11:20. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	860 1,000.00 x 60
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	50.00 30
3	TO REMOVE/REFIT REAR FENDER INNER GARNISH RH	New	80.00 X
4	TO TRANSFER DOOR MECHANISM TO NEW DOOR	New	100.00 80
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	780.00 600
Gross Labour Cost (S\$)			2,010.00

Kan Fook Sing Motor Workshop/SLQ7037S/21/03/2023 11:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6
Akird
104 days
27/03/2023
1524hrs

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 May 2023)

Parts: N/A TOYOTAAQUA 1.5 E 1.5 SA (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SLQ7037S/19/05/2023 16:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER SIDE RETAINER RH	0.00	0.00	*36.00 F
						F=Franchise part.
Sub Total (\$\$)						36.00
+ Margin on L,N Items 10.00% (\$\$)						3.60
Total Parts (\$\$)						39.60

Kan Fook Sing Motor Workshop/SLQ7037S/19/05/2023 16:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Kan Fook Sing Motor Workshop/SLQ7037S/19/05/2023 16:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >