



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, Singapore 533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003939118-01	Date of Loss:	18/03/2023
Vehicle Reg. No.:	SLQ7037S	Driveable?	
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	PANG HEE TENG	Contact No:	+6584685165
Driver:	PANG HEE TENG		

Make/Model:	TOYOTA AQUA, 1.5 E 1.5 SA (A)	Vehicle Reg. Date:	20/07/2017
Vehicle Colour:	METALLIC BLUE		
Engine No:	1NZ8192776	Chassis No:	NHP106602876
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	10

Description of Accident/Loss	REFER WITH ATTAC
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)

COST OF CLAIMS

	Amount
Parts	3,165.80
Miscellaneous Items	0.00
Labour	1,010.00
Paintwork Labour	1,000.00
Towing	0.00
Calculated Gross Total (S\$)	5,175.80
- Excess (S\$)	500.00
(S\$)	4,675.80
+ GST 8.00% (S\$)	374.06
Nett Amount (S\$)	5,049.86

This claim is handled by: MT TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 Mar 2023)

Parts: N/A TOYOTAAQUA 1.5 E 1.5 SA (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SLQ7037S/21/03/2023 11:20

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT FENDER RH	0.00	0.00	*190.00 F SCR X
2	10		*FRONT FENDER SHIELD CLIP	0.00	0.00	nn *25.00 F X
3	1		*FRONT DOOR RH	0.00	0.00	440 ✓ *680.00 F DT ✓
4	1		*FRONT DOOR FAME STICKER RH	0.00	0.00	NEC *28.00 F ? ✓
5	1		*FRONT DOOR OUTER MOULDING RH	0.00	0.00	nn X *120.00 F ?
6	1		*FRONT DOOR RUN CHANNEL RH	0.00	0.00	CUT *70.00 F ? ✓
7	1		*FRONT DOOR SIDE MIRROR RH	0.00	0.00	✓ *265.00 F Miss ✓
8	1		*FRONT DOOR SIDE MIRROR COVER RH	0.00	0.00	✓ *40.00 F Miss ✓
9	1		*REAR DOOR RH	0.00	0.00	✓ *400.00 F XRL
10	1		*REAR DOOR FAME STICKER RH	0.00	0.00	NEC *25.00 F ? ✓
11	1		*REAR DOOR GLASS RH	0.00	0.00	220 ✓ *250.00 F XRL
12	1		*REAR DOOR OUTER MOULDING RH	0.00	0.00	CUT *35.00 F ? ✓
13	1		*REAR DOOR RUN CHANNEL RH	0.00	0.00	60 ✓ *85.00 F ?
14	1		*REAR FENDER RH	0.00	0.00	✓ *480.00 F DT ✓
15	1		*REAR LAMP RH	0.00	0.00	nn *185.00 F X
Sub Total (\$\$)						2,878.00
+ Margin on L,N Items 10.00% (\$\$)						287.80
Total Parts (\$\$)						3,165.80

F=Franchise part.

Kan Fook Sing Motor Workshop/SLQ7037S/21/03/2023 11:20. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	860 ✓ 1,000.00 1,000.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	50.00 30 ✓
3	TO REMOVE/REFIT REAR FENDER INNER GARNISH RH	New	50 ✓ 80.00 80.00
4	TO TRANSFER DOOR MECHANICISM TO NEW DOOR	New	100.00 80 ✓
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	780.00 600 ✓
Gross Labour Cost (S\$)			2,010.00

Kan Fook Sing Motor Workshop/SLQ7037S/21/03/2023 11:20. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Akid

6 ~~24~~ days

27/03/2023

1524hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: