

SPEEDWERKZ PRIVATE LIMITED
 1 KAKI BUKIT AVENUE 6 , #01-73 , AUTOBAY , SINGAPORE 417883
 Tel: 96195936 / info@speedwerkz.biz

*not Allowed
 21/3/23
 1/5 \$2800
 4 days*

VEHICLE NUMBER : GBD9131B
 MAKE & MODEL: TOYOTA HIACE
 DOA: 19/3/2023
 CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
REAR FLOOR BOARD PANEL	1	\$2,381.40	X
REAR SIDE PANEL @1810 RH	1	\$1,813.60	✓
REAR BUMPER	1	\$498.00	✓
REAR BUMPER SIDE RETAINER @60.80	2	\$121.60	✓
REAR BUMPER LOWER SUPPORT BRACKET @56.20	4	\$224.80	X
REAR TAILLAMP @3120 RH	1	\$352.30	X
REAR TAILLAMP GARNISH @1850 RH	1	\$219.00	X
TAILLAMP LOWER GARNISH RETAINER @4920 RH	1	\$49.20	X
TAILLAMP PANEL @1820 RH	1	\$282.70	X

\$5,942.60
 Less 25 % \$1,485.65
 Sub Total \$4,456.95

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR METAL FLOOR BOARD PANEL	1	\$1,600.00	X
REAR SIDE METAL PANEL @1850	1	\$1,850.00	X
REAR BUMPER CLIP	1	\$50.00	30
REAR WINDSCREEN GLASS SEALANT RH	1	\$120.00	40

Sub Total \$3,620.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$100.00	20
APPLY ANTI RUST CHEMICAL		\$250.00	40
REMOVE AND REFIX REAR WINDSCREEN GLASS RH		\$150.00	100
REMOVE AND REFIX REAR FLOOR MAT ETC		\$350.00	11 X
LABOUR CHARGE KNOCK DENTS ON REAR DAMAGE PORTION CUT, WELDING AND		\$2,200.00	900
TO SPRAY PAINT AFFECTED PORTION		\$1,800.00	700

Sub Total \$4,850.00

Grand Total \$12,926.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

*P-23257
 243
 1744.27
 70
 1760
 3574.27
 201
 2800*