



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI23002904/Uvy3m4

Date: 30/03/2023

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 1322U	Veh. Inspected	SMR 1008Z
Policy No.	D22099240	Coverage (\$)	0.00
Claim No.	D23000983MFCV	Excess (\$)	0.00
Assign From	HARMINDER KAUR	Assign Date	21/03/2023

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLC250 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WDC2539462F633673	Colour	BLACK
Odometer	63177 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/60 R18	PIRELLI	6 mm
L/H Front Tyre	235/60 R18	PIRELLI	6 mm
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/03/2023	Inspection Date	23/03/2023
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**