

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Krishnan Bhuvaneshwari

Date: 29 Mar 2023

Preliminary Advice

Vehicle No	: SJL5321J	Accident Date	: 12/03/2023
Make	: TOYOTA RAV4	Policy No.	: D19MPC0004890_03
Assignment Date	: 21/03/2023	Excess	: S\$750.00
Date of Inspection	: 24/03/2023	Est. Duration of Repair	: 5
Inspection At	: LOH HENG (HQ) 176 SIN MING DRIVE, #03-08 SIN MING AUTO CARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,180.43 (inclusive supp \$494.10)
Revised Amount	:S\$	5,321.90
Check Items (Estimated)	:S\$	2,318.55
Total	:S\$	7,640.45

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	47,122.00
Salvage Value	:S\$	
Margin for Repair	:S\$	64,878.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Kindly approve on supplementary.