

LOH HENG

Automotive Repair Services
Accident Insurance Claims

20 March 2023

India International Insurance Pte Ltd

Singapore

Attn. : Motor Claim Department

Re : 1 Estimate Quote (Own Damage)

Vehicle no. SJL5321J Toyota RAV4

A314-32-1



DDR4



Precision touchpad



802.11ac



1000Mbps

Faster memory speed

Faster wireless

Gigabit Ethernet

• Intel® Celeron® processor N4020
 • Intel® UHD Graphics
 • 4 GB DDR4 Memory • 128GB SSD

*Not Authorized
Resurvey before
5 days
11 Pm @ 5050k*

S/N	Description	Amount (\$)
Parts Replacement		
	Front right door <i>1752.80</i>	<i>B1</i> \$ 2,083.30
	Rear right door <i>1752.80</i>	<i>B1</i> \$ 2,083.30
	Right side door inner trim	<i>Tm</i> \$ 1,462.70
	Front right side door regular window <i>341.20</i>	<i>D11</i> \$ 559.60
	Rear right side door regular window <i>341.20</i>	<i>D11</i> \$ 559.60
	Front right door window motor <i>682.40</i>	<i>Tm</i> \$ 986.10
	Rear right door window motor <i>682.40</i>	<i>Tm</i> \$ 986.10
	Front right side door lock	<i>R</i> \$ 897.70
	Rear right side door lock	<i>R</i> \$ 897.70
	Front right side door handle	<i>Sm</i> \$ 543.10
	Rear right side door handle	<i>Rm</i> \$ 543.10
	Front right door hinge (upper)	<i>R</i> \$ 389.30
	Front right door hinge (lower)	<i>R</i> \$ 389.30
	Rear right door hinge (Upper)	<i>R</i> \$ 345.20
	rear right door hinge (lower)	<i>R</i> \$ 345.20
	Front right door moulding protector	<i>CM</i> \$ 321.90
	Front rear door moulding protector	<i>MLM</i> \$ 321.90
		\$ 13,715.10
	less 25%	
	Labour Charges	\$ 10,286.70
	To remove and replace new doors parts. Panel beating and knock out central pillar readjustment and realignment doors.	\$ 980.00
	To rustproofing and seal joints on the affected area	<i>NZ</i> \$ 120.00
	TO putty and respray inside and outside new doors and the affected area	\$ 1,000.00
	To transfer front right doors mechanism, window, channels, etc into new door	\$ 150.00
	To transfer rear right door mechanism, window, channel, etc into new door	\$ 150.00
	Total:	26,000.70

*—
—
X
—
—
—
—
X
X
X
X
X
X
X
X
X
X
—
—*

*600
X
600
600
600*

Block 176 #03-08 Sin Ming Auto Centre
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

LKK Auto Consultants 2023-07-01
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: