

LOH HENG

Automotive Repair Services
Accident Insurance Claims

20 March 2023

India International Insurance Pte Ltd

Singapore

Attn. : Motor Claim Department

Re : | Estimate Quote (Own Damage)
Vehicle no. SJL5321J Toyota RAV4

*Not Authorized
Resurvey Before
5 days*

S/N	Description	Amount (S\$)
Parts Replacement		
	Front right door	<i>RM</i> \$ 2,083.30
	Rear right door	<i>RM</i> \$ 2,083.30
	Right side door inner trim	<i>RM</i> \$ 1,462.70
	Front right side door regular window	\$ 559.60
	Rear right side door regular window	\$ 559.60
	Front right door window motor	\$ 986.10
	Rear right door window motor	\$ 986.10
	Front right side door lock	<i>R</i> \$ 897.70
	Rear right side door lock	<i>R</i> \$ 897.70
	Front right side handle	<i>RM</i> \$ 543.10
	Rear right side door handle	<i>RM</i> \$ 543.10
	Front right door hinge (upper)	<i>R</i> \$ 389.30
	Front right door hinge (lower)	<i>R</i> \$ 389.30
	Rear right door hinge (Upper)	<i>R</i> \$ 345.20
	rear right door hinge (lower)	<i>R</i> \$ 345.20
	Front right door moulding protector	<i>CM</i> \$ 321.90
	Front rear door moulding protector	<i>RM/CM</i> \$ 321.90
		\$ 13,715.10
	less 25%	
	Labour Charges	\$ 10,286.70
	To remove and replace new doors parts. Panel beating and knock out central pillar readjustment and realignment doors.	\$ 980.00
	To rustproofing and seal joints on the affected area	<i>NZ</i> \$ 120.00
	TO putty and respray inside and outside new doors and the affected area	\$ 1,000.00
	To transfer front right doors mechanism, window, channels, etc into new door	\$ 150.00
	To transfer rear right door mechanism, window, channel, etc into new door	\$ 150.00
	Total:	

Handwritten marks:
 - Double lines under Front right door and Rear right door.
 - X marks next to Right side door inner trim, Front right side door regular window, Rear right side door regular window, Front right door window motor, Rear right door window motor, Front right side door lock, Rear right side door lock, Front right side handle, Rear right side door handle, Front right door hinge (upper), Front right door hinge (lower), Rear right door hinge (Upper), rear right door hinge (lower), Front right door moulding protector, Front rear door moulding protector.
 - X marks next to Front right side door lock, Rear right side door lock, Front right side handle, Rear right side door handle, Front right door hinge (upper), Front right door hinge (lower), Rear right door hinge (Upper), rear right door hinge (lower).
 - Double lines under Front right door moulding protector and Front rear door moulding protector.
 - *60d* next to To remove and replace new doors parts...
 - *X* next to To rustproofing and seal joints...
 - *60d* next to TO putty and respray...
 - *60d* next to To transfer front right doors...
 - *60d* next to To transfer rear right door...

Block 176 #03-08 Sin Ming Auto Centre
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: