

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL	R	Ref:	CS/SMO23002909/Kwy3e2	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	D	Date:	05/04/2023	
			C	Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBL 3321S	Veh. Inspected		SHB 7793T	
	Policy No.	D22MTPCVE001006	Coverage (\$)		0.00	
	Claim No.	CMTD2301134/THE	Excess (\$)		0.00	
	Assign From	HENRY IRENE JAMES	Assign Date		21/03/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS (A)	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTDKB3FU703082712	Colour		WHITE	
	Odometer	547007 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WANLI		7 mm	
	L/H Front Tyre	195/65 R15	WANLI		7 mm	
	R/H Rear Tyre	195/65 R15	WANLI		9 mm	
	L/H Rear Tyre	195/65 R15	WANLI		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	19/03/2023	Inspection Date		21/03/2023	
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD			
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair				
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				