

NOT WITHAW
C/Smp @ 3750h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7793T

AAD2303-

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

21 MAR 2023

SHB7793T

JTDKB3FU703082712

200303878K

TOYOTA

PRIUS

19/03/2023

GBL33215 / Somp

16/8/2019

PART

- 1 PANEL SUB-ASSY, FRONT DOOR, LH
- 1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH
- 1 HANDLE ASSY, FRONT DOOR OUTSIDE, LH
- 1 WEATHERSTRIP, FRONT DOOR, LH
- 1 HINGE ASSY, FRONT DOOR, LOWER LH
- 1 HINGE ASSY, FRONT DOOR, UPPER LH
- 1 TAPE, BLACK OUT, NO.1 FRT LH
- 1 TAPE, BLACK OUT, NO.2 FRT LH
- 1 TAPE, BLACK OUT, NO.3 FRT LH
- 1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH
- 1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH
- 1 PANEL SUB-ASSY, REAR DOOR, LH
- 1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, LH
- 1 HANDLE ASSY, REAR DOOR OUTSIDE, LH
- 1 WEATHERSTRIP, REAR DOOR OPENING TRIM, LH
- 1 HINGE ASSY, REAR DOOR, LOWER LH
- 1 HINGE ASSY, REAR DOOR, UPPER LH
- 1 TAPE, BLACK OUT, NO.1 REAR LH
- 1 TAPE, BLACK OUT, NO.2 REAR LH
- 1 TAPE, BLACK OUT, NO.3 REAR LH
- 1 HUB CAP
- 1 PANEL SUB-ASSY, QUARTER, LH
- 1 LINER, REAR WHEEL HOUSE, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH

184.8052

LIST

- \$ 1,641.36 ✓
- \$ 243.81 X
- \$ 493.40 X
- \$ 292.32 X
- \$ 139.86 X
- \$ 123.06 X
- \$ 16.91 ✓
- \$ 55.02 ✓
- \$ 33.29 ✓
- \$ 1,161.83 X
- \$ 300.62 X
- \$ 1,634.33 ✓
- \$ 243.81 X
- \$ 123.06 X
- \$ 369.60 508.12
- \$ 109.62 X
- \$ 124.74 ✓
- \$ 27.62 ✓
- \$ 44.00 ✓
- \$ 19.43 ✓
- \$ 222.08 X
- \$ 1,099.46 X
- \$ 176.09 X
- \$ 624.54 X

TOTAL \$ 9,319.85

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7793T

AAD2303-

25%	\$	2,329.96
	\$	6,989.89

Special Nett

2SET DOOR TRIM CLIP	\$	nn	70.00	X
2SET DOOR WEATHERSTRIP CLIP	\$	nn	130.00	X
1 DOOR STICKER TRANSCAB	\$	nn	100.00	60.00
1 DOOR STICKER TEL NO.	\$	nn	100.00	60.00
1SET CLIP, ROCKER PANEL MOULDING	\$	nn	65.00	X
1SET FRT DOOR ADVERTISEMENT	\$	nn	200.00	100.00
1SET REAR DOOR ADVERTISEMENT	\$	nn	200.00	100.00
1SET FENDER CLIP	\$	nn	130.00	X
1 FENDER LINER CLIP	\$	nn	65.00	X
TOTAL	\$		1,060.00	
TOTAL PARTS	\$		2,300.00	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	60.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	50.00
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	80.00
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	20.00

Trans-cab Auto Services Pte Ltd

AAD2303-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7793T

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To remove and refit of rear fender fittings, attachment and perform water seepage test. \$ *nn* 170.00 X

TOTAL \$ **4,550.00**

Over All Total \$ **13,839.89**

(PART-BY-PART) Repair Days

~~08~~ Days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: