



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|----------------------------|--|
| UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909 | | | Ref: CS/UOI23002910/Uwy3e2 | |
| | | | Date: 19/05/2023 | |
| | | | Code: UOI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | WA 8888A | Veh. Inspected | SMK 7753C | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | M11D00022304 | Excess (\$) | 0.00 | |
| Assign From | JOANNE YONG | Assign Date | 21/03/2023 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA SHUTTLE (A) | c.c | 1496 | |
| Engine No. | HIDDEN | Year of Reg. | 2019 | |
| Chassis No. | GK82001218 | Colour | WHITE | |
| Odometer | 64516 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/50 R16 | FIRENZA | 6 mm | |
| L/H Front Tyre | 205/50 R16 | FIRENZA | 6 mm | |
| R/H Rear Tyre | 205/50 R16 | FIRENZA | 6 mm | |
| L/H Rear Tyre | 205/50 R16 | FIRENZA | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND ROOFTOP. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 20/03/2023 | Inspection Date | 08/05/2023 | |
| Survey held at | JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 3 Working Days | |