

Proforma Invoice / Estimation

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No: LKK-P00002	Date: May 29 2023
	Ticket No: LKK-J000059	Vehicle No: SLU 3550G
	Policy No: 0	Claim No: 0
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Customer: Kinetic Locomotive Pte Ltd Vehicle: HONDA SHUTTLE 1.5 [2017] 2017 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 64811522 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	FRONT BONNET	Part	1.00	550.00	429.00	121.00	484.00	484.00
2	FRONT BONNET SEAL RUBBER	Part	1.00	30.00	23.40	6.60	26.40	26.40
3	FRONT BONNET HINGE LH	Part	1.00	40.00	31.20	8.80	35.20	35.20
4	FRONT BONNET HINGE RH	Part	1.00	40.00	31.20	8.80	35.20	35.20
5	FRONT HEADLIGHT UNIT LH	Part	1.00	1,450.00	1,131.00	319.00	1,276.00	1,276.00
6	FRONT HEADLIGHT UNIT RH	Part	1.00	1,450.00	1,131.00	319.00	1,276.00	1,276.00
7	FRONT GRILLE BASE	Part	1.00	195.00	152.10	42.90	171.60	171.60
8	FRONT GRILLE LOWER MOULDING	Part	1.00	165.00	128.70	36.30	145.20	145.20
9	FRONT BUMPER COVER	Part	1.00	650.00	507.00	143.00	572.00	572.00
10	FRONT BUMPER UPPER BEAM LH	Part	1.00	55.00	42.90	12.10	48.40	48.40
11	FRONT BUMPER UPPER BEAM RH	Part	1.00	55.00	42.90	12.10	48.40	48.40
12	FRONT BUMPER SIDE SPACER LH	Part	1.00	18.00	14.04	3.96	15.84	15.84
13	FRONT BUMPER SIDE SPACER RH	Part	1.00	18.00	14.04	3.96	15.84	15.84
14	FRONT FENDER LH	Part	1.00	195.00	152.10	42.90	171.60	171.60
15	FRONT BUMPER CLIPS	Part	1.00	50.00	40.00	10.00	40.00	40.00
16	(H) EMBLEM	Part	1.00	28.00	21.84	6.16	24.64	24.64
17	FRONT NUMBER PLATE & FRONT NUMBER PLATE BASE	Part	1.00	45.00	36.00	9.00	36.00	36.00
							Taxable Value	4,422.32
							Discount Total	1,105.58
							Grand Total	4,422.32

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
18	LABOUR TO REMOVE, REPLACE / REPAIR, REALIGN AND REFIX THE LISTED ACCIDENT AFFECTED / DAMAGED PARTS	Labour	-	500.00	207.68	292.32	207.68	207.68
19	TO CHECK, RECTIFY AND REALIGN FRONT HEADLAMP UNIT, WIRING AND CONNECTORS IN PROPER WORKING CONDITION	Labour	-	20.00	20.00	0.00	20.00	20.00
20	LABOUR TO PUTTY, RESPRAY PAINT AND POLISH FRONT BONNET, FRONT BUMPER, FRONT BOTH LH AND RH FENDER AND OTHERS AFFECTED AREA	Labour	-	800.00	800.00	0.00	800.00	800.00
							Taxable Value	1,027.68
							Discount Total	292.32
							Grand Total	1,027.68

	Parts Total	4,422.32
	Labour Total	1,027.68
	GST Total	0.00
	Grand Total	5,450.00
	Balance	5,450.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature