

Date : 21/3/2023
Vehicle No: SLU3550G
Model: HONDA SHUTTLE
Chassis: GP7-1121680
Reg. Year: 2017
Policy No: D22MFL0008937
Date of Accident: 18/3/2023
Estimator: SIMON KOH

TO MOTOR CLAIM DEPT
INDIA INT. INSURANCE PTE LTD
64 CECIL STREET #04,#05
IOB BUILDING
SINGAPORE 049711

*Not Noted in
11 Apr @ 5450h
Penny After Pain*

*Ex TBA
5 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT \$S	AMOUNT \$S
1	FRONT BONNET	1	\$550.00	1x \$550.00
2	FRONT BONNET SEAL RUBBER	1	\$30.00	1x \$30.00
3	FRONT BONNET HINGE LH	1	\$40.00	1x \$40.00
4	FRONT BONNET HINGE RH	1	\$40.00	1x \$40.00
5	FRONT BONNET INSULATOR	1	\$125.00	1x \$125.00
6	BONNET OPENER STAY	1	\$35.00	1x \$35.00
7	HOOD STAY GROMMET	1	\$5.00	1x \$5.00
8	FRONT BONNET LOCK COVER	1	\$95.00	1x \$95.00
9	FRONT HEADLIGHT UNIT LH	1	\$1,450.00	1x \$1,450.00
10	FRONT HEADLIGHT UNIT RH	1	\$1,450.00	1x \$1,450.00
11	FRONT GRILLE COVER	1	\$55.00	1x \$55.00
12	FRONT GRILLE BASE	1	\$195.00	1x \$195.00
13	FRONT GRILLE LOWER MOULDING	1	\$165.00	1x \$165.00
14	(H) EMBLEM	1	\$28.00	1x \$28.00
15	FRONT BUMPER COVER	1	\$650.00	1x \$650.00
16	FRONT BUMPER LOWER GRILLE	1	\$85.00	1x \$85.00
17	FRONT BUMPER LIP SPOILER	1	\$95.00	1x \$95.00
18	FRONT FOG LAMP GARNISH LH	1	\$35.00	1x \$35.00
19	FRONT FOG LAMP GARNISH RH	1	\$35.00	1x \$35.00
20	FRONT BUMPER UPPER BEAM LH	1	\$55.00	1x \$55.00
21	FRONT BUMPER UPPER BEAM RH	1	\$55.00	1x \$55.00
22	FRONT BUMPER SIDE SPACER LH	1	\$18.00	1x \$18.00
23	FRONT BUMPER SIDE SPACER RH	1	\$18.00	1x \$18.00
24	FRONT BUMPER BEAM	1	\$325.00	1x \$325.00
25	FRONT FENDER LH	1	\$195.00	1x \$195.00
26	FRONT FENDER RH	1	\$195.00	1x \$195.00
27	FRONT FENDER ENCLOSURE LH	1	\$38.00	1x \$38.00
28	FRONT FENDER ENCLOSURE RH	1	\$38.00	1x \$38.00
SUB TOTAL				\$6,100.00
COST +10%				\$610.00
PARTS TOTAL				\$6,710.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500
Tel: (+65) 6464 9919 | Fax: (+65) 6481 1903

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 21/3/2023
Vehicle No: SLU3550G
Model: HONDA SHUTTLE
Chassis: GP7-1121680
Reg. Year: 2017
Policy No: D22MFL0008937
Date of Accident: 18/3/2023

TO MOTOR CLAIM DEPT
INDIA INT. INSURANCE PTE LTD
64 CECIL STREET #04,#05
IOB BUILDING
SINGAPORE 049711

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT NUMBER PLATE	1	\$25.00	25.00
2	FRONT NUMBER PLATE BASE	1	\$35.00	35.00
3	FRONT BUMPER CLIPS	1	\$50.00	50.00
S/N TOTAL				\$110.00

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN AND REFIX THE LISTED
ACCIDENT AFFECTED/DAMAGED PARTS

\$1,000.00

TO CHECK, RECTIFY AND REALIGN FRONT HEADLAMP UNIT, WIRING AND
CONNECTORS IN PROPER WORKING CONDITION

\$150.00

LABOUR TO PUTTY, RESPRAY PAINT AND POLISH FRONT BONNET, FRONT
BUMPER, FRONT BOTH LH AND RH FENDER AND OTHERS AFFECTED AREA

\$1,000.00

TO TUFF KOTE AND UNDERSEAL MATERIALS

\$180.00

LABOUR TOTAL \$2,330.00

TING AN TOTAL \$9,150.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Branch (Motor Insurance Claims)

BLK 10 Ang Mo Kio Rd, Park 2A 401-05 Singapore 680047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1003

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112