



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2304630

INV Date 19/07/2023

Reference CC4/LPC23002913/Aya3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLA 3020A
Insured Veh. SGU 59M
Claim No. 22/23/23/VP05/027141
Policy No. Z22VP05031146
Accident Date 18/03/2023
Inspection Date 21/03/2023

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC23002913/Aya3q2 Date: 19/07/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGU 59M	Veh. Inspected	SLA 3020A	
Policy No.	Z22VP05031146	Coverage (\$)	0.00	
Claim No.	22/23/23/VP05/027141	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	21/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0327965	Colour	WHITE	
Odometer	162081 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/60 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/60 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/60 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/03/2023	Inspection Date	21/03/2023	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 3020A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DISTORTED	1,074.80	1,074.80
1	REAR BUMPER SIDE HOLDER- RH	DAMAGED	38.80	38.80
1	REAR BUMPER TOW COVER	MISSING	33.60	33.60
1	REAR BUMPER REFLECTOR -RH	CRACKED	54.50	54.50
1	REAR BUMPER REINFORCEMENT	DENTED	537.30	537.30
1	REAR END PANEL	DISTORTED	559.60	559.60
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	185.10	-
1	TAILLAMP -RH	CRACKED	915.20	915.20
1	TAILLAMP PANEL -RH	DENTED	377.80	377.80
1	BOOTLID	TO REPAIR SEE LABOUR	957.40	-
1	BOOTLID LOCK	NOT NECESSARY	164.60	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	156.90	-
1	BOOTLID REFLECTOR -RH	CRACKED	445.70	445.70
1	MAZDA LOGO	NECESSARY	64.20	64.20
1	MAZDA 3 WORDING	NECESSARY	58.90	58.90
1	SKYACTIV EMBLEM	NECESSARY	60.90	60.90
1	REAR FENDER RH	DISTORTED	1,294.70	1,294.70
1	REAR FENDER INNER SHIELD -RH	NOT NECESSARY	142.20	-
1	REAR FENDER INNER TRIM BOARD -RH	NOT NECESSARY	323.40	-
1	REAR FENDER AIR VENT -RH	DEFORMED	78.20	78.20
1	REAR WINDSCREEN MOULDING	NECESSARY	168.40	168.40
1	REAR EXHAUST PIPE	NOT NECESSARY	1,024.70	-
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	35.10	-
1	REAR EXHAUST PIPE GASKET	NOT NECESSARY	30.90	-
	LESS 20% DISCOUNT		-1,756.58	-1,152.52
			7,026.32	4,610.08
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-

Report Ref No. CC4/LPC23002913/Aya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	SET REAR FENDER INNER SHIELD CLIPS -RH (SN)	NOT NECESSARY	20.00	-
1	SET REAR FENDER INNER TRIM BOARD CLIPS -RH (SN)	NOT NECESSARY	30.00	-
1	REAR FENDER SEALANT -RH (SN)	NECESSARY	60.00	60.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
			560.00	210.00
	LABOUR			
	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS .INCLUSIVE OF THE REPAIR OF BOOTLID .		1,600.00	1,200.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,600.00	1,300.00
	TO CHECK WIRING SYTEM.		100.00	30.00
	TO SPRAY TUFF COAT.		150.00	80.00
	TO REMOVER REVERSE SENSOR .		100.00	50.00
	TO REMOVE UPHOLSTERY .		150.00	60.00
	TO REMOVE REAR WINDSCREEN .		180.00	120.00
	TO REMOVE EXHAUST PIPE .	NOT NECESSARY	150.00	-
	TO TRANSFER BOOTLID FITTINGS .	NOT NECESSARY	150.00	-
			4,180.00	2,840.00
GRAND TOTAL			11,766.32	7,660.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,100.00

Report Ref No. CC4/LPC23002913/Aya3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 3020A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLA 3020A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

