

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

LONPAC INSURANCE BHD

300 Beach Road #17-04/07
The Concourse
Singapore 199555
Tel : 6250 - 7388
Fax : 6296 - 2706

Quotation

DATE : 21.03.2023
VEH NO : SLA3020A
MODEL : Mazda 3
D O A : 18.03.2023
YR REF : SGU59M

Ezlyn

Attn : Motor Claim Dept

(Pls arrange vehicle surveyor & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLA3020A (MAZDA 3)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted.</i>	1	1,074.80 ✓
2	Rear Bumper Side Holder - RH <i>Dmgd</i>	1	38.80 ✓
3	Rear Bumper Tow Cover <i>Missing</i>	1	33.60 ✓
4	Rear Bumper Reflector - RH <i>crackd</i>	1	54.50 ✓
5	Rear Bumper Reinforcement <i>Dented</i>	1	537.30 ✓
6	Rear End Panel <i>Distorted</i>	1	559.60 ✓
7	Rear End Panel Top Garnish <i>new</i>	1	185.10 +
8	Taillamp - RH <i>crackd</i>	1	915.20 ✓
9	Taillamp Panel - RH <i>Dented.</i>	1	377.80 ✓
10	Bootlid <i>Rev</i>	1	957.40 +
11	Bootlid Lock <i>new</i>	1	164.60 +
12	Bootlid Weatherstripe	1	156.90 +
13	Bootlid Reflector - RH <i>crackd</i>	1	445.70 ✓
14	Mazda Logo <i>new</i>	1	64.20 ✓
15	Mazda 3 Wording <i>new</i>	1	58.90 ✓
16	SkyActiv Emblem	1	60.90 22.20 ✓
17	Rear Fender - RH <i>Distorted</i>	1	1,294.70 ✓
18	Rear Fender Inner Shield - RH <i>new</i>	1	142.20 X
19	Rear Fender Inner Trim Board - RH	1	323.40 X
20	Rear Fender Air Vent - RH <i>Dented</i>	1	78.20 ✓
21	Rear Windscreen Moulding <i>new</i>	1	168.40 ✓
22	Rear Exhaust Pipe <i>new</i>	1	1,024.70 X
23	Rear Exhaust Pipe Mounting <i>new</i>	1	35.10 +
24	Rear Exhaust Pipe Gasket	1	30.90 +
			\$ 8,366.40
Less 20%			(1,673.28)
			\$ 6,693.12

5762.60

S/NETT ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SLA3020A (MAZDA 3)

1	Rear Bumper Clips <i>new</i>	1 set	30.00	✓
2	Reverse Sensor <i>new</i>	1 set	280.00	✓
3	Rear End Panel Top Garnish Clips <i>new</i>	1 set	20.00	✓
4	Rear End Panel Sealant <i>new</i>	1 set	60.00	✓
5	Rear Fender Inner Shield Clips - RH <i>new</i>	1 set	20.00	✓
6	Rear Fender Inner Trim Board Clips - RH <i>new</i>	1 set	30.00	✓
7	Rear Fender Sealant - RH <i>new</i>	1	60.00	✓
8	Rear Windscreen Sealant <i>new</i>	1	60.00	✓

Total Parts \$ 7,253.12

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,600.00	1200
2	To putty & spray up paint works	\$	1,600.00	1300
3	To check wiring system	\$	100.00	30
4	To spray tuff coat	\$	150.00	80
5	To remove reverse sensor	\$	100.00	50
6	To remove upholstery	\$	150.00	60
7	To remove rear windscreen	\$	180.00	120
8	To remove exhaust pipe	\$	150.00	x.
9	To transfer bootlid fittings	\$	150.00	x.

Total Labour \$ 4,180.00

Grand Total \$ 11,433.12

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 8812.60
h/s 7050
09 Days