

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

LONPAC INSURANCE BHD

300 Beach Road #17-04/07
The Concourse
Singapore 199555
Tel : 6250 - 7388
Fax : 6296 - 2706

Quotation

DATE : 21.03.2023
VEH NO : SLA3020A
MODEL : Mazda 3
D O A : 18.03.2023
YR REF : SGU59M

Ezlyn

Attn : Motor Claim Dept

(Pls arrange vehicle surveyor & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLA3020A (MAZDA 3)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted.</i>	1	1,074.80 ✓
2	Rear Bumper Side Holder - RH <i>Dmgd</i>	1	38.80 ✓
3	Rear Bumper Tow Cover <i>Missing</i>	1	33.60 ✓
4	Rear Bumper Reflector - RH <i>crackd</i>	1	54.50 ✓
5	Rear Bumper Reinforcement <i>Dented</i>	1	537.30 ✓
6	Rear End Panel <i>Distorted</i>	1	559.60 ✓
7	Rear End Panel Top Garnish <i>new</i>	1	185.10 +
8	Taillamp - RH <i>crackd</i>	1	915.20 ✓
9	Taillamp Panel - RH <i>Dented.</i>	1	377.80 ✓
10	Bootlid <i>Rev</i>	1	957.40 +
11	Bootlid Lock <i>new</i>	1	164.60 +
12	Bootlid Weatherstripe	1	156.90 +
13	Bootlid Reflector - RH <i>crackd</i>	1	445.70 ✓
14	Mazda Logo <i>new</i>	1	64.20 ✓
15	Mazda 3 Wording <i>new</i>	1	58.90 ✓
16	SkyActiv Emblem	1	60.90 22.20 ✓
17	Rear Fender - RH <i>Distorted</i>	1	1,294.70 ✓
18	Rear Fender Inner Shield - RH <i>new</i>	1	142.20 X
19	Rear Fender Inner Trim Board - RH	1	323.40 X
20	Rear Fender Air Vent - RH <i>Dented</i>	1	78.20 ✓
21	Rear Windscreen Moulding <i>new</i>	1	168.40 ✓
22	Rear Exhaust Pipe <i>new</i>	1	1,024.70 X
23	Rear Exhaust Pipe Mounting <i>new</i>	1	35.10 +
24	Rear Exhaust Pipe Gasket	1	30.90 +
			\$ 8,366.40
Less 20%			(1,673.28)
			\$ 6,693.12

5762.60

S/NETT ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SLA3020A (MAZDA 3)

1	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
2	Reverse Sensor <i>new</i>	1 set	280.00 ✓
3	Rear End Panel Top Garnish Clips <i>new</i>	1 set	20.00 ✓
4	Rear End Panel Sealant <i>new</i>	1 set	60.00 ✓
5	Rear Fender Inner Shield Clips - RH <i>new</i>	1 set	20.00 x
6	Rear Fender Inner Trim Board Clips - RH <i>new</i>	1 set	30.00 +
7	Rear Fender Sealant - RH <i>new</i>	1	60.00 ✓
8	Rear Windscreen Sealant <i>new</i>	1	60.00 ✓

Total Parts \$ 7,253.12

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 1,600.00 <i>1200</i>
2	To putty & spray up paint works	\$ 1,600.00 <i>1300</i>
3	To check wiring system	\$ 100.00 <i>30</i>
4	To spray tuff coat	\$ 150.00 <i>80</i>
5	To remove reverse sensor	\$ 100.00 <i>50</i>
6	To remove upholstery	\$ 150.00 <i>60</i>
7	To remove rear windscreen	\$ 180.00 <i>120</i>
8	To remove exhaust pipe	\$ 150.00 x.
9	To transfer bootlid fittings	\$ 150.00 x.

Total Labour \$ 4,180.00

Grand Total \$ 11,433.12

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hereby notifies the Repairer of the following:

- To survey before/after and during repair
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

total: 8812.60
h/s 7050
09 Days