

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001852453-01	Date of Loss:	18/03/2023
Vehicle Reg. No.:	SLD634H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Lee Ee Yang	Contact No:	+6598594333
Driver:	Lee Ee Yang		
Make/Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Vehicle Reg. Date:	31/05/2016
Vehicle Colour:	Red		
Engine No:	PE20779354	Chassis No:	JM6GJ1072G0237900
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Remarks:	VEHICLE IS IN		
Present Location:	CITY AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	5,036.90
Miscellaneous Items	0.00
Labour	1,785.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	6,821.90
- Excess (S\$)	600.00
(S\$)	6,221.90
+ GST 8.00% (S\$)	497.75
Nett Amount (S\$)	6,719.65

This claim is handled by: **VRONICA**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Mar 2023)

Parts: 143 MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: City Auto Pte Ltd/SLD634H/21/03/2023 15:55

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front LH fender	0.00	0.00	*165.00 F
2	1		*Front LH fender brace bracket	0.00	0.00	*38.00 F
3	1		*Front LH fender innershield	0.00	0.00	*65.00 F
4	12		*Front LH fender innershield clip	0.00	0.00	*24.00 F
5	1		*LH headlamp	0.00	0.00	*1,450.00 F
6	1		*Front bumper	0.00	0.00	*600.00 F
7	2		*Front bumper retainer	0.00	0.00	*30.00 F
8	1		*Front bumper LH chrome	0.00	0.00	*85.00 F
9	1		*Front bumper LH fog cover	0.00	0.00	*55.00 F
10	1		*Front bumper lower grille	0.00	0.00	*45.00 F
11	10		*Front bumper clip	0.00	0.00	*20.00 F
12	8		*Front bumper rivet	0.00	0.00	*32.00 F
13	1		*Front grille base LH	0.00	0.00	*95.00 F
14	1		*Front grille chrome LH	0.00	0.00	*80.00 F
15	1		*Front LH rim	0.00	0.00	*650.00 F
16	1		*Front LH tyre	0.00	0.00	*225.00 F
17	1		*Front LH wheel bearing	0.00	0.00	*285.00 F
18	1		*Front LH knuckle arm	0.00	0.00	*225.00 F
19	1		*Front LH lower arm	0.00	0.00	*215.00 F
20	1		*Front LH shock absorber	0.00	0.00	*195.00 F

F=Franchise part.

Sub Total (\$\$)	4,579.00
+ Margin on L,N Items 10.00% (\$\$)	457.90
Total Parts (\$\$)	5,036.90

City Auto Pte Ltd/SLD634H/21/03/2023 15:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	- To check wiring and lighting	New	60.00
2	- To remove and refit front LH suspension unit	New	200.00
3	- To conduct wheel alignment	New	75.00
4	- To knock jackout damaged parts, panel beating, align, refix and to renew accident parts	New	600.00
5	- Spray painting on affected and replace parts	New	850.00
Gross Labour Cost (\$\$)			1,785.00

City Auto Pte Ltd/SLD634H/21/03/2023 15:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >