

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 22 Mar 2023

**Preliminary Advice**

Vehicle No	: SLD634H	Accident Date	: 18/03/2023
Make	: MAZDA 6	Policy No.	: SP2001852453-01
Assignment Date	: 21/03/2023	Excess	: S\$600.00
Date of Inspection	: 22/03/2023 (DESKTOP SURVEY)	Est. Duration of Repair	: 5 DAYS
Inspection At	: CITY AUTO PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,821.90
Revised Amount	:S\$	4,194.40
Check Items (Estimated)	:S\$	555,30
Total	:S\$	4,749.70

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	59,000.00
COE / PARF Rebate	:S\$	30,302.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,698.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Part by Part repair. According to the repairer, there are no second-hand parts available. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.