

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001852453-01	Date of Loss:	18/03/2023
Vehicle Reg. No.:	<b>SLD634H</b>	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Lee Ee Yang	Contact No:	+6598594333
Driver:	Lee Ee Yang		
<hr/>			
Make/Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Vehicle Reg. Date:	31/05/2016
Vehicle Colour:	Red		
Engine No:	PE20779354	Chassis No:	JM6GJ1072G0237900
Odometer:	0 KM		
<hr/>			
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	<del>7</del> 5		
<hr/>			
Remarks:	VEHICLE IS IN		
Present Location:	CITY AUTO PTE LTD (HQ)		
<hr/>			

COST OF CLAIMS	Amount
Parts	5,036.90
Miscellaneous Items	0.00
Labour	1,785.00
Paintwork Labour	0.00
Towing	0.00
<hr/>	
<b>Calculated Gross Total (S\$)</b>	<b>6,821.90</b>
- Excess (S\$)	600.00
<hr/>	
(S\$)	6,221.90
+ GST 8.00% (S\$)	497.75
<hr/>	
<b>Nett Amount (S\$)</b>	<b>6,719.65</b>

**This claim is handled by: VRONICA**

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2023)
<b>Parts:</b> 143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> City Auto Pte Ltd/SLD634H/21/03/2023 15:55	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front LH fender	0.00	0.00	*165.00 F	BUC
2	1		*Front LH fender brace bracket	0.00	0.00	*38.00 F	?
3	1		*Front LH fender innershield	0.00	0.00	*65.00 F	CRA
4	12		*Front LH fender innershield clip	0.00	0.00	*24.00 F	NEC
5	1		*LH headlamp	0.00	0.00	*1,450.00 F	CUT
6	1		*Front bumper	0.00	0.00	*600.00 F	BUC
7	2		*Front bumper retainer	0.00	0.00	*30.00 F	NEC
8	1		*Front bumper LH chrome	0.00	0.00	*85.00 F	XHC
9	1		*Front bumper LH fog cover	0.00	0.00	*55.00 F	XNN
10	1		*Front bumper lower grille	0.00	0.00	*45.00 F	XNN
11	10		*Front bumper clip	0.00	0.00	*20.00 F	NEC
12	8		*Front bumper rivet	0.00	0.00	*32.00 F	XNN
13	1		*Front grille base LH	0.00	0.00	*95.00 F	XNN
14	1		*Front grille chrome LH	0.00	0.00	*80.00 F	XAN
15	1		*Front LH rim	0.00	0.00	*650.00 F	CUT
16	1		*Front LH tyre	0.00	0.00	*225.00 F	XNN
17	1		*Front LH wheel bearing	0.00	0.00	*285.00 F	XNN
18	1		*Front LH knuckle arm	0.00	0.00	*225.00 F	XNN
19	1		*Front LH lower arm	0.00	0.00	*215.00 F	XNN
20	1		*Front LH shock absorber	0.00	0.00	*195.00 F	XNN

F=Franchise part.

<b>Sub Total (\$)</b>	<b>4,579.00</b>
<b>+ Margin on L,N Items 10.00% (\$)</b>	<b>457.90</b>
<b>Total Parts (\$)</b>	<b>5,036.90</b>

City Auto Pte Ltd/SLD634H/21/03/2023 15:55. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	- To check wiring and lighting	New	30 60.00
2	- To remove and refit front LH suspension unit	New	200.00
3	- To conduct wheel alignment	New	75.00
4	- To knock jackout damaged parts, panel beating, align, refix and to renew accident parts	New	600.00
5	- Spray painting on affected and replace parts	New	400 850.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,785.00</b>

City Auto Pte Ltd/SLD634H/21/03/2023 15:55. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 5 DAYS

- NOT AUTHORISE
- EXCESS \$ 600
- P/P OR L/S REPAIR?
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: