

Date: 17/03/2023

Vehicle No: SLU3098X

Model: HONDA FREED HYBRID 1.5G

Chassis: GB71048294-2017

Reg. Year: 2017

Third Party Insurer: ALLIANZ

Third Party Veh No: SMG2515C

Date of Accident: 16/03/2023

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR LH	1	BT/way	\$972.20
2	REAR DOOR PROTECTIVE STICKER LH	1	na	\$45.30
3	REAR DOOR RUBBER SEAL LH	1		\$88.50
4	REAR FENDER LH	1	R	\$969.70
5	REAR RIM COVER LH	1	na	\$197.90
6	REAR BUMPER	1	R	\$876.70
7	REAR BUMPER SIDE BRACKET LH	1	R	\$34.80
8	FRONT DOOR LH	1		REPAIR
SUB TOTAL				\$3,185.10
LESS 20%				-\$637.02
PARTS TOTAL				\$2,548.08

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR INNER TRIM BOARD CLIPS LH	1		na \$50.00
2	REAR FENDER QUARTER GLASS SEALANT LH	1		na \$80.00
3	REAR BUMPER CLIPS	1		\$50.00
S/N TOTAL				\$180.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554600
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 17/03/2023
 Vehicle No: SLU3098X
 Model: HONDA FREED HYBRID 1.5G
 Chassis: GB71048294-2017
 Reg.Year: 2017

Third Party Insurer: ALLIANZ
 Third Party Veh No: SMG2515C
 Date of Accident: 16/03/2023
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

500
\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR LH, REAR DOOR LH, REAR FENDER LH, REAR BUMPER & ETC.

800
\$1,000.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR LH.

60
\$120.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER QUARTER GLASS LH, REAR FENDER QUARTER GLASS SEALANT & ETC.

~ \$150.00 X

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH, UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH.

\$250.00 60

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 30

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 20

LABOUR TOTAL \$2,720.00

TING AN

TOTAL

\$5,448.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

8 Kiang Chong Road Singapore 156143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6491 1522 | Fax: (+65) 6481 1011

