

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23002933/AVP3M4**Date:** 10/04/2023**REFERENCE**

Insured/Claimant:	CHIN MAY HIANG	Policy No:	2100454915-07	
Date of Loss:	18/03/2023	Nature of Claim:	OD	Claim No: 7188805299SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA4469H		
Make & Model:	AUDI A3 SB, 1.4 TFSI AMBIENTE (A)	Engine No:	CZC515128
Reg. Date:	29/02/2016 (Man. Year: 2015)	Chassis No:	WAUZZZ8V6GA095683
Colour:	White	Odometer:	106638 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$53,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	600.00	600.00	0.00	0.00
Nett Amount (\$\$)	-600.00	-600.00	0.00	0.00

INSPECTION

Date of Assignment:	24/03/2023		
Date Inspected:	21/03/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	0.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$53,000.00
OMV :	\$26,919.00
PARF Rebate (1) :	\$11,812.00
Quota Premium Paid :	\$44,001.00
COE Rebate (2) :	\$12,925.00
Total Rebate (1) + (2) = :	\$24,737.00

The total amount incurred will be Market Value \$53,000.00 minus Total Rebate \$24,737.00 = \$28,263.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >