

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: ALLIANZ INSURANCE SINGAPORE PTE LTD

12 MARINA VIEW

#04-01, ASIA SQUARE TOWER 2

SINGAPORE 018961

Registration No : SMM6756R

Chassis No Model

: MRHFC5650KT000546 : CIVIC 1.6 VTI YM2019 : LAI YAOBING NICHOLAS

Owner's Name

<u>Item</u>

Ins Policy No.

Date of Accident

: 21/3/2023

Document No. Date

Customer No.

Qtv

: SQT23000857

: 21. Mar 2023

: WZA011

Svc Advisor : ANIKKA LAI SWEE KAM

: R16B25510587 **Engine No** : 21. Mar 2023 6:42:32 PM

Unit Price Disc %

Date | Time

Surveyor Name

25

25

25

25

25

25

Sum Item

Survey Date Authorisation Date

579.90

10.40

10.40

2.30

75.90

675.90

100.00

160.00

1000.00

1000.00

CM 1

8% GST Amount Amount

Not Mishoria Mermy BEpaing 3day

434.92

7.80

7.80

17.25

56.92

506.92

1031.61

100.00

160.00

2260.00

650 1000.00

520 1000.00

34.79

0.62

0.62

1.38

4 55

40.55

82.51

8.00

12.80

80.00

80.00

180.80

QUOTATION GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Amount incld GST

469.71

8.42

8.42 1

18.63

61.47

547.47 7

108.00 206

1,114.12

172.80

1080.00

1080.00

2,440.80

3,554.92

Page

Description TP DIRECT SETTLEMENT (J/NO:

OWNER: LAI YAOBING NICHOLAS

OWNER INSURER: AUTO & GENERAL INS

ACC DATE: 21/03/2023 SURVEYED BY:

DATE: REF NO:

TP INSURER: ALLIANZ TP VEH: SMG7053K

71101-TEA-T50ZA	FACE,FR.BUMPER	
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	
91505-TM8-003	CLIP,BUMPER	
71180-TBA-K50	GARNISH ASSY,R.FR.BUMPER SIDE	
33100-TEC-Q01	HEADLIGHT ASSY,R.	

BOSUN	SUNDRIES	1
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1
BKBU01R	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	

ON 1	
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1 (1P)	

10.25gm

1	A D	1	
1			
j			
		LK	
		Total (
		plan	١
			•

Total Amount	3,291,61
K Auto Consultants	hence notify

263 31 3,554.92

religion of the following: · To resurvey before/after spray painting

Sum Labor

To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Cignature:

Care

Survey By	Kenner
Date & Time	4/4/23
Excess	

Printed on 21/3/2023 6:51:16 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.0

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.