

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Mar 2023 19:38	Clm Veh Model Changed		[] Merimen Administrator
2	15 Mar 2023 19:38	Clm Created	Reg No: SMT357L. Policy No: 2070054674-01. Acct Date: 2023/02/15. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS: SP14233F0001	[I] Merimen Administrator
3	16 Mar 2023 13:51	Clm Registration Modified	Acct Date:2023/02/15->2023/03/15. Acct Time:08:30:00->08:00:00. Pol No:2070054674-01->2070054674. Init.Est.:->4,000 - 5,000.	[I] Toh, Yuslinda
4	16 Mar 2023 13:51	Clm Veh Model Changed	(203437) AUDI Q3 2.0 TFSI (A).	[I] Toh, Yuslinda
5	22 Mar 2023 11:22	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Rajeswari
6	22 Mar 2023 11:22	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Rajeswari
7	22 Mar 2023 11:22	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Rajeswari
8	22 Mar 2023 11:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2023/03/31	[A] Rajeswari
9	22 Mar 2023 11:22	Adj Mandate Set	Approved:0.00.Reinspr:Adj decides.	[A] Rajeswari
10	22 Mar 2023 11:22	Clm Registration Modified	Rep:1137->200611.	[A] Rajeswari
11	22 Mar 2023 11:22	Clm Veh Model Changed	(203437) -> (205236) AUDI Q2 999cc 1.0 TFSI S TRONIC (A).	[A] Rajeswari
12	22 Mar 2023 11:23	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Rajeswari
13	23 Mar 2023 09:01	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
14	23 Mar 2023 09:01	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
15	23 Mar 2023 09:01	Clm Dtl Modified	JPJ Reg. Date: -> 2020/03/25.	[A] Elaine Kuan Hwa Meen
16	23 Mar 2023 09:01	Clm Details Notified		[A] Elaine Kuan Hwa Meen
17	23 Mar 2023 09:58	Clm Registration Modified	Excess: -> 400.00. Excess Waived: -> 400.00. 2F Remarks: -> Not Applicable. GST: -> 8.00.	[I] Hiew, Chasin
18	23 Mar 2023 10:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2023/03/31	[A] SHIAU CHAN
19	23 Mar 2023 10:01	Adj Mandate Request	Cur.Req:17492.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUT HORISE REPAIR.	[A] SHIAU CHAN
20	24 Mar 2023 08:32	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2023/03/31. Mandate Remarks: Vehicle may commence repair - To retake Left Headlamp damage photo - refer Adrian Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before	[I] Lim, Kok-Chong
21	24 Mar 2023 08:32	Adj Mandate Set	Approved:15407.00:Vehicle may commence repair - To retake Left Headlamp damage photo - refer Adrian Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels an	[I] Lim, Kok-Chong

Date From Date To Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2936194	23 Mar 2023 09:01:30	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMT357L		11.00

