

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0272/2023/EQ
DATE : 15-Mar-23
WIP : 11835

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S PREMIUM AUTOMOBILES PTE LTD
ADDRESS : 55 UBI ROAD 1
SINGAPORE 408699

TELEPHONE : HP +65 66900293
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SNF 9574 D**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 30/6/2022
ENGINE NO : DEM 024337
CHASSIS NO : WAUZZZF40LA071609
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Mar-23
PLACE OF ACCIDENT : PIE, SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 9574 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 700.00	500
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	500
4	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS. <i>✓ R.H Fender ✓</i>	\$ 3,500.00	1650
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>7,672.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

4004984

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9574 D

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deh</i>	1	\$ 2,515.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 416.00	X.
3	FRONT BUMPER SECURING STRIP - LH / RH ?	2	\$ 84.00	?
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 231.00	X
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 310.00	X
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 166.00	t
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE ?	1	\$ 310.00	?
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 318.00	X.
9	FRONT BUMPER OUTER GRILLE HOLE COVER - LH / RH ?	2	\$ 114.00	?
10	RADIATOR GRILLE <i>could</i>	1	\$ 1,861.00	✓
11	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 953.00	?
12	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 224.00	?
13	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 86.00	X.
14	FRONT BUMPER TOP COVER <i>could</i>	1	\$ 151.00	✓
15	CAUTION SIGN STICKER <i>3 per</i>	1	\$ 17.00	✓
16	AIR CONDITIONER STICKER	1	\$ 9.00	✓
17	FRONT BUMPER BRACKET ?	1	\$ 163.00	?
18	FRONT BUMPER SUPPORT - LH / RH ?	2	\$ 68.00	?
19	FRONT PARKING AID SENSOR - INNER / OUTER <i>2 per</i>	2	\$ 543.00	X
20	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 11.00	t
SUB TOTAL SPARE PARTS			\$ 8,550.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 9574 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	BONNET <i>new</i>	1	\$ 3,489.00	+	
22	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 455.00	+	
23	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i>	3	\$ 101.00	+	
24	BONNET STRIKER - LH / RH	2	\$ 120.00	+	
25	BONNET LOCK - LH / RH	2	\$ 481.00	+	
26	BONNET BOWDEN CABLE <i>new</i>	1	\$ 67.00	+	
27	BONNET RELEASE LEVER	1	\$ 16.00	+	
28	BONNET BOWDEN CABLE - CENTER <i>new</i>	1	\$ 67.00	+	
29	BONNET RELEASE CABLE COVER <i>new</i>	1	\$ 12.00	+	
30	HEADLAMP COVER - LH / RH <i>new</i>	2	\$ 104.00	+	
31	HEADLIGHT - LH / RH <i>crackd</i>	2	\$ 17,332.00	✓	
32	LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 488.00	+	
33	LIFT CYLINDER CORRUGATED PIPE <i>new</i>	1	\$ 111.00	+	
34	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 22.00	+	
35	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 76.00	?	
36	RADIATOR AIR GUIDE - LH / RH ?	2	\$ 50.00	?	
37	RADIATOR AIR GUIDE - UPPER ?	1	\$ 25.00	?	
38	RADIATOR AIR GUIDE - LOWER ?	1	\$ 38.00	?	
39	FRONT NUMBER PLATE <i>Dented</i>	S/N	\$ 60.00	✓	
40	SUNDRIES ?		\$ 400.00	?	

TOTAL SPARE PARTS	:	\$	32,064.00
TOTAL LABOUR CHARGES	:	\$	7,672.00
GRAND TOTAL	:	\$	39,736.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *21/03/23*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and approved from Insurance Company
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT