

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 20.03.2023

TO : SCDF MOTOR CLAIMS DEPTS
VEHICLE NO : SJZ2249G
MODEL : TOYOTA COROLLA ALTIS
DATE OF ACCIDENT : 19.03.2023
TIME OF ACCIDENT : 17:40 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 498.00	\$ 498.00
2	REAR BUMPER REFLECTOR LH <i>cracked</i>	1	\$ 60.00	\$ 60.00
3	REAR BUMPER RETAINER (FRONT) <i>new</i>	2	\$ 70.00	\$ 140.00
4	REAR BUMPER SIDE RETAINER (BACK) <i>LH Dmgd</i>	2	\$ 78.00	\$ 156.00
5	REAR BUMPER BRACKET <i>LH Distorted</i>	2	\$ 90.00	\$ 180.00
6	REAR BUMPER SPONGE <i>Cracked</i>	1	\$ 140.00	\$ 140.00
7	REAR BUMPER PROTECTOR BAR <i>Not new</i>	1	\$ 395.00	\$ 395.00
8	REAR FENDER LH <i>Buckled</i>	1	\$ 980.00	\$ 980.00
9	REAR FENDER INNER COWLING LH <i>Not new</i>	1	\$ 350.00	\$ 350.00
10	REAR FENDER INNER TRIM LH <i>Not new</i>	1	\$ 370.00	\$ 370.00
11	REAR FENDER AIR VENT LH <i>Cracked</i>	1	\$ 148.00	\$ 148.00
12	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 110.00	\$ 110.00
13	TAILLAMP LH <i>Cracked</i>	1	\$ 330.00	\$ 330.00
14	TAILLAMP PANEL LH <i>Re Buckled</i>	1	\$ 198.00	\$ 198.00
15	TAILLAMP LOWER BARCKET LH <i>cracked</i>	1	\$ 45.00	\$ 45.00
16	BOOTLID <i>Buckled</i>	1	\$ 780.00	\$ 780.00
17	BOOTLID LAMP LH <i>wt</i>	1	\$ 226.00	\$ 226.00
19	BOOTLID LOGO	1	\$ 65.00	\$ 65.00
20	BOOTLID EMBLEM '1.6'	1	\$ 40.00	\$ 40.00
22	BOOTLID EMBLEM 'COROLLA'	1	\$ 50.00	\$ 50.00
23	BOOTLID EMBLEM 'ALTIS'	1	\$ 50.00	\$ 50.00
24	BOOTLID STOPPER <i>Not new</i>	2	\$ 18.00	\$ 36.00

TO : **SCDF** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJZ2249G**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 19.03.2023
 TIME OF ACCIDENT : 17:40 HOURS

25	BOOT LID HINGE <i>3 New</i>	2	\$ 70.00	\$ 140.00	<i>+</i>
27	BOOTLID TOP LOCK <i>1 New</i>	1	\$ 125.00	\$ 125.00	<i>+</i>
28	BOOTLID LOWER LOCK <i>1 New</i>	1	\$ 20.00	\$ 20.00	<i>+</i>
29	BOOTLID WEATHERSTRIP <i>1 New</i>	1	\$ 195.00	\$ 195.00	<i>✓</i>
30	REAR END PANEL <i>1 New</i>	1	\$ 595.00	\$ 595.00	<i>✓</i>
31	REAR END PANEL TOP GARNISH <i>1 New</i>	1	\$ 220.00	\$ 220.00	<i>✓</i>
32	REAR FLOOR PANEL TOP BOARD <i>1 New</i>	1	\$ 298.00	\$ 298.00	<i>✓</i>
33	REAR FLOOR SIDE PANEL LH <i>1 New</i>	1	\$ 240.00	\$ 240.00	<i>+</i>

5196
3897

TOTAL PRICE \$ 7,180.00
 LESS 25% \$ 1,795.00
SUB TOTAL PRICE \$ 5,385.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>1 New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
2	REAR BUMPER CLIP (SET) <i>1 New</i>	1	\$ 80.00	\$ 80.00	<i>30</i>
3	BOOT LID INSULATOR CLIP (SET) <i>1 New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
4	TAILLAMP CLIPS (SET) <i>1 New</i>	1	\$ 40.00	\$ 40.00	<i>10</i>
5	TAILLAMP PANEL SEALANT <i>2 New</i>	2	\$ 60.00	\$ 120.00	<i>20</i>
6	REAR FENDER RH SEALANT <i>1 New</i>	1	\$ 150.00	\$ 150.00	<i>40</i>
7	REAR FENDER COWLING CLIP (SET) <i>1 New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
8	REAR FENDER INNER TRIM CLIP (SET) <i>1 New</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
9	REAR WINDSCREEN SEALANT <i>1 New</i>	1	\$ 80.00	\$ 80.00	<i>40</i>
10	REAR WINDSCREEN INNER SEAL <i>1 New</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
11	REAR END PANEL TOP GARNISH CLIP (SET) <i>1 New</i>	1	\$ 40.00	\$ 40.00	<i>10</i>
12	REAR END PANEL INSULATION SEAL <i>1 New</i>	1	\$ 150.00	\$ 150.00	<i>60</i>
13	REVERSE SENSOR <i>1 New</i>	1	\$ 220.00	\$ 220.00	<i>20</i>
14	REVERSE CAMERA <i>1 New</i>	1	\$ 580.00	\$ 580.00	<i>+</i>

440

TOTAL \$ 1,840.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>1200</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>1000</i>

TO : **SCDF** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJZ2249G**
 MODEL : **TOYOTA COROLLA ALTIS**
 DATE OF ACCIDENT : 19.03.2023
 TIME OF ACCIDENT : 17:40 HOURS

3	TUFF COAT	\$ 250.00	80.
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	60
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	X
7	TRANSFER BOOTLID MECHANISM	\$ 80.00	60
8	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
9	REMOVE & REINSTALL REAR WINDSCREEN	\$ 120.00	✓
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	60
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL

\$5,200.00

2630 Adnan Li
 E/S 21/03/23.
 09 Days

TOTAL PARTS COST : \$ 7,225.00
 TOTAL LABOUR COST : \$ 5,200.00
 TOTAL REPAIR COST : \$ 12,425.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6967
 2/S: 5550 ✓